


One of the fracture surfaces from the coupling was sectioned and prepared for examination using the Scanning Electron Microscope (SEM). The fracture appeared to have originated in the area adjacent to the spring plunger. The fracture progressed around and through the coupling. SEM examination revealed areas of cup cone topography around the majority of the fracture surface. Where the coupling finally broke, areas of shear overload were present (Figure 5). No other anomalies were noted on the fracture surface which might have contributed to the fracture.



4. A fracture occurred at the coupling (4D00253G01) between fin tip pole 4 (4D00368H06) and fin tip pole 5 (4D00368H07). The fracture surface exhibited shear lips around the entire circumference of the tube. The fracture travelled around the weld bead that holds the spring plunger. Dirt deposits were present on the inner diameter of the coupling. There were no signs of corrosion around the area of fracture (Figure 6).




Figure 6 - Overall view of the coupling between fin tip pole 4 and fin tip pole 5 showing the location of the fracture (top left, shown at $\sim 0.12X$). Close-up views showing the fracture (top right, shown at $\sim 0.75X$ and bottom right, shown at $\sim 0.37X$).

One of the fracture surfaces from the coupling was sectioned and prepared for examination using the Scanning Electron Microscope (SEM). The fracture appeared to have originated in the area adjacent to the spring plunger. The fracture progressed around and through the coupling. SEM examination revealed areas of cup cone topography around the majority of the fracture surface. Where the coupling finally broke, areas of shear overload were present (Figure 7). No other anomalies were noted on the fracture surface which might have contributed to the fracture.




Figure 7 – Sample from the coupling that was examined using the SEM. SEM views showing tensile overload (views A, B and C) and shear overload features (view D) seen on the surface.

Material Analysis- All the fin tip pole assembly components that exhibited fractures were analyzed for material composition using X-ray Fluorescence ((XRF)). XRF analysis revealed that fin tip pole joint 2 and both couplings from fin tip poles 1 & 2 and fin tip poles 4 & 5 were aluminum based, with magnesium, silicon, copper, chromium, iron, manganese and zinc present as alloying constituents. Quantitative analysis matched with the general requirements of a 6061 aluminum alloy. The engineering drawing's call out for 6061-T6 Aluminum as the required material is vague. It should specify 6061-T6 Aluminum per a known specification (i.e., SAE AMS 2770).

The outer diameter, inner diameter and wall thickness dimensions of the fin tip pole joint 2, and both couplings from fin tip poles 1 & 2 and fin tip poles 4 & 5 were obtained using calibrated calipers. All the dimensional requirements provided by the engineering drawings were met.

Hardness Tests- The fin tip pole joint 2, coupling between pole sections 1 & 2 and the coupling between pole sections 4 & 5 were subjected to hardness testing. Table 1 shows the results of the testing.

TABLE 1

	Hardness Rockwell "15T"
Fin tip pole joint 2	80.5
Coupling – Poles 1 & 2	80.7
Coupling – Poles 4 & 5	81.2

The engineering drawing did not specify hardness requirements for the components of the fin tip pole assembly. AMS 2658C was used as a guide to determine if the components met hardness requirements. Table 1 provides hardness and conductivity acceptance values for aluminum alloys. The requirement for 6061 in the T6 condition is 78.0 Hardness Rockwell scale "15T" minimum. The values obtained on the tested samples met this requirement.

Metallographic Examination- Mounted cross sections of the fin tip pole joint 2 and both couplings were used for metallographic examination. Examination up to 800X did not find any discontinuities within the microstructure that could have contributed to the failure. The microstructures were judged to be normal for 6061 in the T6 condition (Figure 8).






Figure 8 – Metallographic views showing the microstructures of the fin tip pole joint 2 (top left, shown at 200X) and the couplings from fin tip poles 1 & 2 (top right, shown at 200X) and fin tip poles 4 & 5 (bottom right, shown at 200X). All the samples were etched using Keller's etchant.

All parts were returned to the AIB investigator.

NATICK LABS Field Investigation Report



(b)(5)





(b)(5)




(b)(5)

(b)(5)






(b)(5)




(b)(4)




(b)(5)

(b)(5)




(b)(5)






(b)(5)





(b)(5)



(b)(5)


(b)(5)





(b)(5)

(b)(5)




(b)(5)


(b)(5)


(b)(5)

(b)(5)




(b)(5)







(b)(5)




(b)(5)




(b)(5)




(b)(5)



(b)(5)



(b)(5)



(b)(5)



**DEPARTMENT OF THE ARMY
PROGRAM EXECUTIVE OFFICE, MISSILES AND SPACE
BUILDING 5250
REDSTONE ARSENAL, AL 35898-8000**

SFAE-MSL-CM

MEMORANDUM FOR RECORD

SUBJECT: Joint Land Attack Cruise Missile Defense Elevated Netted Sensor System (JLENS)
Failure Review Board (FRB) Report

Referred to PEO, Missiles & Space, Redstone

SFAE-MSL-CM
SUBJECT: JLENS FRB Results

Referred to PEO, Missiles & Space, Redstone

SFAE-MSL-CM
SUBJECT: JLENS FRB Results



SFAE-MSL-CM

SUBJECT: JLENS FRB Results

Referred to PEO, Missiles & Space, Redstone

SFAE-MSL-CM
SUBJECT: JLENS FRB Results

Referred to PEO, Missiles & Space, Redstone

(b)(6)


Failure Review Board Chairperson

- Aerostat weight and balance maintained with Orbit payload weights and locations
 - Documented in EDTM-731

74A FCR REV 36

WEIGHT SUMMARY #1				WEIGHT SUMMARY #1				WEIGHT SUMMARY #1			
	WEIGHT (lbs)	POSITION X (ft)	POSITION Y (ft)		WEIGHT (lbs)	POSITION X (ft)	POSITION Y (ft)		WEIGHT (lbs)	POSITION X (ft)	POSITION Y (ft)
Aerostat				"A" Aerostat				"A" Aerostat			
"A" Aerostat Mechanical	7606.590	109.312	0.033	"A" Aerostat Mechanical				"A" Aerostat	7606.590	109.312	0.033
"B" Aerostat Riggng	893.670	83.547	0.617	"B" Aerostat Riggng				"B" Aerostat	83.547	0.617	4.137
"C" Aerostat Electrical	251.610	74.650	0.726	"C" Aerostat Electrical				"C" Aerostat	351.610	74.650	0.719
"D" Housekeeping Rack	1196.340	80.549	0.000	"D" Housekeeping Rack				"D" Housekeeping Rack	1196.340	80.549	0.000
"E" Windscreen Payload Frame	237.000	121.390	0.000	"E" Windscreen Payload Frame				"E" Windscreen Payload Frame	237.000	121.390	0.000
"W" Aerostat Cables	411.770	65.230	0.031	"W" Aerostat Cables				"W" Aerostat Cables	411.770	83.930	0.270
"X" Ballast	0.100	236.000	0.000	"X" Ballast				"X" Ballast	0.100	236.000	0.000
Aerostat Max Weight	10667.1	Margin Tether Wt		Aerostat Subtotal: 10667.1				Aerostat Subtotal: 10667.1			
	10999.0	301.9	0.577	Aerostat Max Weight for 7000 lb Payload:	10999.0			Aerostat Max Weight for 7000 lb Payload:	10999.0		
Payload #1 (FCR Radar)				Payload #1 (SUR Payload)				Payload #1 (SUR Payload)			
"F" Subtotal Main Payload	4821.000	121.390	0.000	"F" Windscreen Payload Subtotal				"F" Windscreen Payload Subtotal			
"G" Subtotal: Payload Support Equipment	1111.000	93.620	0.000	"G" Payload Support Subtotal				"G" Payload Support Subtotal			
				"J" Port Group Main Payload Subsystem				"J" Port Group Main Payload Subsystem			
				"K" Stbd Group Main Payload Subsystem				"K" Stbd Group Main Payload Subsystem			
				"M" Hull Measurement Subsystem				"M" Hull Measurement Subsystem			
Payload #2 (Comms)								Payload #2 (Comms)			
"H" Subtotal: Lower Communications	754.000	180.910	0.000	21.260				"H" Subtotal: Lower Communications			
"I" Subtotal: CEC	345.000	127.930	0.000	-31.780				"I" Subtotal: CEC			
				Payload #2 Subtotal 10984.000				Payload #2 Subtotal 10984.000			
				Payload Total 7031.000				Payload Total 7031.000			
				7000 lb Allocated Payload Offset -31.000				7000 lb Allocated Payload Offset -31.000			
WEIGHT SUMMARY #2								7000 lb Allocated Payload Offset -165.000			
Aerostat								7000 lb Allocated Payload Offset -165.000			
Payload #1 (FCR Radar)	10697.080	101.375	0.100	11.921				7000 lb Allocated Payload Offset -165.000			
Payload #2 (Comms)	5932.000	116.189	0.000	32.557				7000 lb Allocated Payload Offset -165.000			
	1099.000	164.285	0.000	4.610				7000 lb Allocated Payload Offset -165.000			
SYSTEM TOTAL	17728.080	110.232	0.061	18.373				SYSTEM TOTAL	17882.080	108.387	0.072
7000lb Allocated Payload System Total	17697.080	110.208	0.000	18.355				7000lb Allocated Payload System Total	17697.080	108.300	0.000

Meets Platform Weight Requirement With 302 (2.7%) Margin



Referred to PEO, Missiles & Space, Redstone

Data Restrictions:

Distribution DISTRIBUTION STATEMENT F – Further dissemination only as directed by the Cruise Missile Defense Systems Project Office, SFAE-MSLS-CMDS-PE-CM. Redstone Arsenal, AL 35898-5000, 24 March 2000.



Referred to PEO, Missiles & Space, Redstone

Applicable to: All

UNCLASSIFIED

JLENS-49956-00000-00



Referred to PEO, Missiles & Space, Redstone

Applicable to: All

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

UNCLASSIFIED

JLENS-49956-00000-00

No Authority to Release, Referred to PEO, Missiles & Space, Redstone

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR# or N/A	Defect# or N/A
9/4/15	1515		Latched cut 1515 for incinerator weather and lighting Chpt #2 tripped again. And the monitor close in inc is going out. & it is turning off Soft Shutter	19152	
9/4/15	1710		Power flickered out and came back up on Gcis didn't occur any longer for mins. 40C and what's still up when I went out to check.	21102	
9/5/15	0630		had cell failure confirmed. Cleaned connector w/ no joy. Briefed Army FP + id that we could launched and monitor since part will not be on site till Tuesday 9/8. Army did not want to launch since it was Holiday. No mission, and potential risk. Had team crews hook up priceness as precaution due to multiple power failures on site.		
9-6-15	0500		On site check of system. All is good.		
9-6-15	1600		Launched TBM, SH 695 w/ 15412 L-14 J = 29,608 1.1mbs to 900.2 No issues		
9-6-15	1615		prior to it. changed load cell 9% 3D1683C A01 S/N 1279947 with new load cell S/N 1279947 Component is good.	1293393	

(b)(6)

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9-6-15 2045			LOW WINDS ALLOW INCH TENSORS; TETHER MOVE TO 6497' WHICH LOCATES: HPU 2 FAULT OCCURRED		
9-7-15 0445			TETHER MOVE TO 6801'. HPU 2 FAULT CAME ON FOR A SECOND TIME IN A ROW.		
9-7-15 1145			Tether move to 1005' CP 11370 / winds 10.0 Kts / Temp 54.4°F Scheduled move HPU 2 Fault occurred after HPu Shutdown		
9-8-15 0318			TETHER MOVE FOR WEDGED TENSION TO 8499' 100' / 9,700'/wind 4.3/ TEMP 44.5°F - HPU 2 TRIP AND WAS RESET UPON SHUTDOWN. (b)(6)		
9-8-15 1120			Tether move to 9249' CP 11023 / winds 10.0 Kts / Temp 53.4 °F Scheduled move. HPU 2 Soft start Triped and was reset 1.4' ↓ at altitude = 29,313		
9-8-15 1625			Tether move to 9000' CP 62367 / winds 11.6 Kts / Temp 54.3°F Ops move L, ft = 39, 415		
11-15 2041			TETHER MOVE TO 8748' / CP 11223 / wind 12.4 Kts / temp 56.3°F		
9-9-15 0504			TETHER MOVE TO 10,900' / CP 11,361 / WINDS 18.6 KTS / TEMP 57.8°F		

Page closed by (QA): _____ Date: 9/9/15 (b)(6)

Page - 29 -

NO PILOTS WERE OUT AT

(b)(6)

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9/15/15 01:58			HONY SHOTDOWN DOWNED ON TOP OF FIELD, PITCH + 2320 WING DOWNED; NO WIND TO 34/3 / 40 9987 / WIND 14.4 / 1000 010 A POSITIONAL TENDO LOSS OF DYNAMIC MEASURE ON FIN MUST CARRY MOUNTED - RESTORED ON ITS OWN.		
9/15/15 02:18			ADVISED BOTH THAT FP'S TO RECOVER - COULD DELIVER ONLY IN AND AROUND THIS BAKTMOON AND TRACTOR TO BOTH SITES NO LTR-15		
9/15/15 02:45			RECOVERED FROM FUT 605, THREW IN THE VICINITY FUGIT TIME 83.07 TOTAL TIME 605.603 / 4 FLIGHTS ON TENDER THREE RETURN.		
9/15/15 03:45					
9/15/15 04:08			SM'S CROW REDUCED START STATION 4P2U#12; MC ATTACHED TO PLATEAU IT BOLT AND INTO DIFFICULTY, REMOVED FROM TRAIL ORIGINATE TO 5.12 TO HULL SIDE FIX CARRIER. 1200C ADDED TUBE #3 FROM SMD 405-5 CALCULATED NORTH LIFT 24/349 WING CANTILLET HAVING LOST VARIOUS PART FURTHER.		
9-13-15 11:00			INSPECTED ROTARY DRIVE. EXTERNAL & GEAR NEEDED LUBE		
			ENTRIES TO FOLLOW DESCRIBING TEARAWASHINGS, EFFORTS FROM 9-10-15 TO 9-13-15		

Page closed by (QA): _____ Date: 9/15/15

(b)(6) _____

Page - 31 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9-15-15 1645		(b)(6)	<p>LAUNCHED FLIGHT 606 AT 1438. ROTARY DRIVE FAILED TO DRIVE TO THE RIGHT (CW) DURING THE LAUNCH. NO OTHER ISSUES WITH THIS LAUNCH. ROTARY DRIVE PRESSURE WAS COMPARED AND TWO DRIVE IS 1000 FTS. LESS WHEN OPERATED. WILL BE INSPECTED FURTHER. STOPPED AT 5302 FT.</p> <p>(b)(6)</p> <p>MAN WHICH HPU 2 SOFT STARTER (CAT. NO. 5811) T24N35, SN: 59946622 DOWN FROM COLUMBIA (CAT. NO. 5811+T24N35, SN: 936C3060). THE SAME WAS ALREADY CONFIGURED BY BEAM SLEEVY IN E. CITY. REMOVED EXISTING HPU 2 SOFT STARTER (SN: 5A946621) AND INSTALLED SHARE HPU 2 SOFT STARTER (SN: 936C3060). CONFIGURED HPU 2 WORK ON 5200 SOFTWARE AND DIM INTERFACE UNIT. SYSTEM IS NOW OPERATIONAL.</p> <p>* NOTE!! SOFT STARTER CAT. NO. 5811 IS NO LONGER IN PRODUCTION BY THE MANUFACTURER. THIS MODEL HAS BEEN REPLACED BY CAT. NO. 5811+. DIVERGENT MODEL D770-DNA IS ALSO DISCONTINUED. DUE TO THE PROCESS OF TRANSFERS STARTER SOFT STARTER MODEL 5811+, WE NOTICED THE NEWER MODEL HAS A NEWER FIRMWARE WHICH CAUSES CONFIGURATION MODE COMMUNICATION OF THE UNIT DIFFICULT. THIS COULD BE THE CASE DIVERGENT MODEL D770-DNA IS NOT COMPATIBLE W/ THE NEWER SOFT STARTER 5811+. ANOTHER SOFTWARE IS AUTOTEST. POSSIBLE SOLUTION, VERIFY NEWER SOFT STARTER 5811+ CONTINUED BEFORE RETURN TO SITE AS STATED OR PROVIDE CORRECT HARDWARE/ SOFTWARE TO CONFIRM 5811+ ON SITE.</p> <p>(b)(6)</p>	STR 5811 JES-A9346622 ST15562	

Page - 32 -

000152

EPI-C-16-02-23-Army-FOIA-20170606-Blimp-Report

epic.org

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H483020)	STR # or N/A	Defect# or N/A
9-13-15	2300		Tether move to 5502' / CP 12780 / winds 30.6 Kts / Temp 42.4°F Scheduled move		
9-14-15	0417		Out haul		
9-14-15	0435		Tether move to 1002' / CP 1397 / winds 29.4 Kts / Temp 33.3°F Move to meet mission requirements		
9-14-15	0540		(b)(6) Page 4 Showed EBU 142 activated at 0523. De Activated at 0531L. During this 8 minute time LRU showed 400 Hz operating and EBU's 1, 2, 3 all in the green. Page 4 now shows EBU 1 = .9, EBU 2 = 1.0		
9-14-15	0706		EBU's 1 & 2 ACTIVATED AT 0714. EBU 1 = 1.8 EBU 2 = 1.9 AH.		
9-14-15	0915		" DEACTIVATED AT 0923" EBU 1 = 2.1 EBU 2 = 2.2 AH.		
9-14-15	0925		" DEACTIVATED AT 0935. EBU 1 = 2.5. EBU 2 = 2.7 AH.		
9-14-15	1221		TETHER MOVE TO 9756' / CP 14,493 / WINDS 35.5 KTS / TEMP 48.2°F		
9-14-15	1620		TESTED ROTARY DRIVES. CCW ROTARY DRIVES WITH NO ISSUE. VERIFIED VIA PLUS +1 LAPTOP THAT THE JOYSTICK POSITION IS CORRECT FOR CCW OPERATION TESTED CW ROTARY	JESA 934525 B0001 STR 0562	

Page closed by (QA): _____

(b) (6)

Date: 9/15/15

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR# or N/A	Defect# or N/A
9-14-17 15			DRIVE, WHICH D/D NOT DRIVE DURING THE INITIAL TEST, VERIFIED TOYSICK POSITION WAS CORRECT VIA PLATE #1 LATER. TOYSICK POSITION IN CW DIRECTION MATCHES CCW DIRECTION COMPARED PRESSURES. PRESSURE IN CW IS 1000 - 1200 PSI LOWER THAN CCW DAMPING BLOCK FEEL WARMI, INDICATING THAT FLUID IS BEING SUPPLIED. OPENED CAPSTAN SIDE GEARBOX, OIL SMELLED BURNED. FURTHER WORK MAY BE NEEDED. AFTER SEVERAL TESTS, ROTARY DRIVES WORKED IN BOTH DIRECTION HOWEVER CW ROTATION IS SLUGISH.	JM JESIA 93/5554021 STR 5562	
9-14-17 15			Assy, 074103, EMPIRORAGE SENSOR FAILURE FAULT PRESENT, FOR MOST OF THE FLIGHT.	JM JESIA 93/5554017 STR 5566	
9-14-17 15			(b) (6)		
9-14-17 15			Tether motor 7998 Cap 1110 / Wind 22 Knts / Temp 45.1 F (b) (6)		

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9-15-15	0425		Tether move to 9798' / CP 112409 / winds 14.2 Kts / Temp 46.3 °F Scheduled move J = 29,001		
9/15/15	12:23		target move to 10000 mD / CP 12,744 / wind 11.3 / temp 47.4°		
9-15-15	2020		Tether move to 9099' / CP 10576 / winds 3.5 Kts / Temp 51.4 °F		
9-15-15	2200		Tether move to -101' / CP 10713 / winds 1.9 Kts / Temp 55.7 °F		
9-16-15	0410	(b)(6)	Tether move to 7999' CP 9840 / winds 4.6 Kts / Temp 51.5 °F		
9/16/15	0725		target move to 9,703 / CP 11,676 / wind 6.9 / temp 53.6 °F		
9/16/15	1725		Tether move 9531		
9/16/15	2035		Tether move 91A9 / CP 11047 / wind 10.1 / temp 52.0°		
9-17-15	0555		Recovered Tether left 606 at 0540L. Total fly time 87.03 Total system fly time = 659.0. 09. APG time = 282.53 During recovery at -2799', obtained lead wind fault. After several attempts to reset fault, had to hold down leadwind switch to complete "inhaul". Once married we observed leadwind switch had to make switch position adjustment. - No issues after adjustment	572 5567	

Page closed by (QA): _____ (b)(6) Date: 9/21/15

Page - 35 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
7-17-2015 / 030	(b) (6)		Attempted to install engineering spare HPDU (P/N: 3D16924G01 S/N: M002241, Rev K). The EBUS did not display signs of activation when the heaters were manually turned to ON. However, when the heat was commanded to OFF, the small battery currents occasionally exceeded 1.0 A fluctuating.	STR 5666 TESA152570017	STR 5666 TESA152570017
			Another spare HPDU (S/N: M002841, Rev J) was modified to include 2 copper plate bars. A new label is required to properly identify this unit as Rev K. No issues with installation of this unit. The HPDU removed had Rev: K S/N: M004034	STR 5566 TESA152570017	STR 5566 TESA152570017
9-17-0 1750	(b) (6)		While troubleshooting the HPDU, blower blanket heater #5 CB repeatedly tripped after commanding the heat ON. Swapping HCU units had no effect. Removed FETSU #1 (P/N: 4D00433G01, S/N: M002282, Rev L) and replaced with (S/N: M002281, Rev L). Instead of blower blanket heater #5 tripping when heat is applied, blower blanket #9 trips when heat is activated. Launched Team STR 407 at 1737 L. LSA J = 30, 299 Climbed to 7231	STR 5666 STR 5567	STR 5666 STR 5567

Date	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9/18/15 0300			Tether move 6949 Cp 10369 / Temp. 54°F / winds 5.6 kts		
9/18/15 0840	(b)6		TETHER MOVE TO 162000 / CP 13000 / TEMP 48.2 / WIND 5.3		
9-18-15 1300			Secured wind sock at tower of mms.		
			Inspected JB at nose latch. No water was found. The JB was completely dry. In the process of opening the JB the weather proof seal was damaged. New weatherproof seal must be applied.		
9/18/15 1400	(b)6		MATT LEE AND CASEY TESTED THE ROTARY DRIVE AS PER NICK ANDERSON'S REQUEST. THE ROTARY DRIVE JOYSTICK IN THE WINCH CAB WAS PLACED OUT IN THE COUNTER CLOCKWISE POSITION FOR 5 SECONDS RETURNED TO NEUTRAL FOR 10 SECONDS THEN PLACED OUT IN THE CLOCKWISE POSITION FOR 5 SECONDS AS PER THE ROTARY DRIVE PRESSURE READ OUT ON PAGE 5, COUNTER CLOCKWISE READ 3649 PSI AND CLOCKWISE READ 3,186 PSI.	TR 5562 TO JESAA 9341525800:	
9/18/15 1615	(b)6		TETHER MOVE TO 9849. CP 12,641 / TEMP 57.1°F / WIND 12.3 KTS.		
9/18/15 1900	(b)6		INSPECTED NOSE LATCH VISUALLY w/o DISASSEMBLE. RECEIVER SEEKS SLIGHTLY WORN. BOTH NOSE LINE (TOP 2) PULLEYS SEEM TO HAVE EXCESSIVE PLAY. GREASE IS SPREADING AROUND BEARING SURFACES. MAY NEED TO REFERENCE OR HAVE REPLACEMENT OR HAND.		

Page closed by (QA): _____

(b)6)

Date: 9/21/15

Page - 37 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9-18-15	2045		TETHER MOVE DUE TO LOW WIND TENSIONS. WIND 9.4 KTS	7853	CP 10500/WIND 590016/
9-19-15	0845		TETHER MOVE 107040/		
9-19-15	1301		TETHER MOVE TO 8249 / CP 123 / 524		
9-19-15	2108		TETHER MOVE TO 7699 / CP 10350 / WIND 8.1 KTS / TEMP 58.3°F SCHEDULED MOVE.		
9-20-15	0440		Tether move to 7900 / CP 10835 / winds 14.5 kts / Temp 53.9 °F		
9-20-15	1335	(b) (6)	Tether move to 7499 / CP 12245 / winds 18.7 kts / Temp 65.8 °F		
9-20-15	2145		TETHER MOVE TO 7191 / CP 10165 / WINDS 2.3 KNTS / 54.0°F		
9-21-15	0500		Tether move to 7449 / CP 10491 / winds 3.5 kts / Temp 53.4 °F Scheduled move		
9-21-15	0730		Tether move to 9048 / CP 11416 / winds 12.1 kts / Temp 47.7°F		
9-21-15	1700		TETHER MOVE TO 9318 / CP 11376 / WINDS 7.4 KNTS / TEMP 46°F		
9-22-15	0130		TETHER MOVE TO 9001 / CP 11440 / WINDS 10.1 KNTS / TEMP 48.8°F		

(b) (6)

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9-22-15 0720			Tether move to 9800' / CP 10500 / winds 7.2 KTS / Temp 44.7 °F		
9-22-15 1505			Tether move to 9398		
9-22-15 2445			TETHER MOVE TO 9101' / CP 10900 / WINDS 4.0 KTS / TEMP 52.2 °F		
9-22-15 0813P	(b)(6)		TETHER MOVE TO 8850' / CP 10120 / WINDS 2.4 KTS / TEMP 50.3°F		
9-23-15 1207			Tether move to 9800' / CP 12804 / winds 4.7 KTS / Temp 62.7°F		
9-23-15 1945			TETHER MOVE TO 9000' / WINDS 4.6 KTS / TEMP 52.3°F		
9-23-15 2250			TETHER MOVE TO 8000 FT REPLACED BULB IN MCC READY LIGHT. PRESSURE CONTROL STATUS BRILLY INDICATED RED WHEN INHALER WAS STOPPED. SODIUM RIBER ALARM BEAVER FAULT COULD BE SEEN BEYOND THE RED BORDER.		
9-24-15 0053			PER LOG ENTRY ON 9/16/15 BY C. BOATMAN, WE CONDUCTED ANOTHER RETRACT DRIVE TEST PER NICK AND PERSON'S REQUEST. ADDITIONAL PERIMETER WITS MODIFIED DURING THIS TEST.		
9-24-15 0810P	(b)(6)		TETHER MOVE TO 9798' / CP 10731 / WINDS 6.5 KTS / TEMP 48.5°F SCHEDULE MOVE.		

Page closed by (QA): _____

Date: _____

Page - 39 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9/24/15 1600			TETHER MOVE TO 9549 / CP 11725 / WINDS 5-4 KT / TEMP 55°F SCHEDULED MOVE.		
9/24/15 2045			Tether move to 8001 / CP 11,279 / wind 18.9kt / temp 20.5°F move per request for main com. 25mms		
9/24/15 0420			Tether move to 8500m / CP 11,727 / wind 12.1kt / temp 47.6°F		
9-25-15 0840			Replaced Rotary Drive Valve, Rel. of United Cartridge (2) P/N: RUGS-1521. Tested and Ved good.		
9-25-15 1232	(b)6		Tether move to 8700 CP 11780 / Wind, 13kt / Temp, 57.9°F		
9/25/15 1535			FTC # 1321 Standard size shaded window on winter cab		
9/26/15 20:30			Tether move to 7153 m / CP 12,600 / wind 16.3 / temp 53.0°F		
9/26/15 04:30			Tether move to 7776 m / CP 12,918 / wind 18.4 / temp 48.5°F		
9/26/15 1230			Tether move to 7676 / CP 13162 / winds 23.4 kt / Temp 50.2°F		
9/26/2015			Recovered Tether at 8007 @ 1827 ut for main transop site work plane ✓		

Date	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
7/25/2020 cont.	(b)(6)		RENT. DURING HANG, PROBABLE FUEL LINE DEFECT HYDRAULIC LINE IN AND OUT OF TUBE. ADVISED AIRCRAFT FD TO REPAIR. TUBING CANTILEVER WAS FORMED. LAUNCHED FROM FET COS C 1920 hrs 10/7/2023 FST - THEY THEN DECIDED TO SIMPLY PUNCTURE HYDRAULIC LINE DOWN IN THIS MANNER AS/AND NOMAD. DURING THIS TIME THE TETHER DESTROYED INDICATION WAS RESTORED. TFD MARCHED SPURS OUT TO ENABLING NAVIGATION.		
7/26/2020			COURT TACKLE/HOOKINGS ON AWP. AFTER REPAIRS THE LCM SCREAMS TO BE NOTED IMPACT WHICH MOVES THE BACKSTRIKE ON THE TOP OF THE BACKSTRIKE RECORDED 4 TGS. REP FOR REPAIR.		
7/27/2020	1220	(b)(6)	Normal move to COSPI 700 / CP 11634 / and 124 / 1000 55.6°		
7/27/2020	1300		Tether move to Lengasi / CP 12139 / winds 12.1 kts / Temp 54.2 °F Scheduled move		
7/27/2020	2020		United Rentals came to site to inspect AWP. Found "brown" O-Ring seal causing leak. O-Ring was replaced. Normal move to 6,244 rd / CP 11,193 / and 12.0 kts / 1000 55.6°		

Page closed by (QA): _____

Date: _____

Page - 41 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9/28/15 0816			Tethered now to 7614, CP 10, 220, and G. 9150, 55.8° F Tether move to 7713; CP 11482 / winds 7.3 kts / Temp. 53.7 ° F Scheduled move		
9/28/15 1200		(b) (6)	Recovered Team CH 609 at 1155 L. Recovery due to army request to perform cert. of system. Total fit time = 16.58. Total system time = 6847.51, Total A/C time = 531.95		
9/28/15			Army Training & Cert S/Hs AT launch Time		
			609 1210 1240 .40 610 1254 1310 .37 611 1434 1454 .30 612 1457 1513 .27		
		(b) (6)	REMOVED AND REPLACE FITSU #1 TO CORRECT THE PROBLEM WITH THE HEATER BLAQUEZ FOR THIS BLOWER. TURNED ON THE HEATER CONTROL UNIT TO MANUAL D/R AND NOW OF BLAQUEZ BREAKER TRIP. ALSO BLOWDOWN #2 IS WORKING AS WELL. (REMOVED FITSU #1 P/N 4D004336P1 FROM REV. L SHM002081) (INSTALLED REV. M SHM001573 AEROSTAT BACK TO OPERATIONAL STATUS.		
			1/28/15 1640		

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
7-28-15	1730		RE-INSPECTED NOSE LINE SHEATHES ON TOWER UNDER TENSION OF LAUNCH AND RE-CLOUDY. SHEATHES SEEM LOOSE ON BEARING SURFACE BUT WERE 100% OPERATIONAL DURING OPERATION. THIS IS AN ITEM THAT WILL NEED MONITORING FROM TIME TO TIME; MAY STILL WANT TO ORDER REPLACEMENTS.	21302	
7/29/15 2036			MOTORED TEAM FET 6/3 @ 18:17 local AND RECOVERED FET 6/3 @ 18:34 local FOR HELICOPTER RE-CLOUDS SIGHTS IT 65849.13 (3 RDS ON ROAD)	00302 9/29	
7/29/15 2037			LANDED TEAM AT 6/4 @ 19:08 local TO 6583 RECD-7D -P 10,242 435/ wind 11.3 ESD/ temp 55.5°F	00372 9/29	
7/29/15 2048		(b)(6)	TOWER MOVE TO 5978 msl/ eop 10,773 /wind 13.5 ESD/ temp 54.7°F - OCTOBER 08182		
7/29/15 2050			RE-COVERED FLIGHT 6/4 AT 0749 TO SUPPORT Army CERS SORTED LAUNCHED FLIGHT 6/5 FROM 0852 TO 0921, FLIGHT 6/6 FROM 0931 TO 0951 AND FLIGHT 6/7 AT 0953. CERTS WERE STOPPED WITH TIC ACROSTAT AT 2004 FT TO ALLOW NOSE AND BONN HIPS TO close.	14102	
7/29/15 2130			RE-COVERED FLIGHT 6/7 TO THE MTS.2 SOLDIERS WILL BE ENTERING THE WINDSCREEN TO LOAD OCTOBER CRYPTO,	16302	
7/29/15 2132		(b)(6)	2 SOLDIERS AND (b)(6) (RAYTHEON) ENTERED THE WINDSCREEN TO UPLOAD OCTOBER CRYPTO, ALONG WITH TOOLS AND ONE LADDER.	17292	

Page closed by (QA): _____

Date: _____

Page - 43 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
9/29/15	1350		2 SAUNDERS AND TOOLS AND ONE LADDER.	19002	
9/30/15	0509	(b) (6)	LAUNCHED FLIGHT C18 @ 0649 LOCAL TIME. TETHER DEPROTED 5200' CP-12,607/ WINDS-272 KTS / TEMP- 63.3°F — BORGARD DANGAGED TETHER MOVE TO 5500' / CP 11,493 / WINDS 16.4 KTS / TEMP 68.3°F	09092	
9/30/15	1235		RECOVERED FROM FT 618 BECAUSE OF A HUMICATE IN THE BATHROOMS ?? ANYHOW NO ISSUES IT 6881.84	0035 1011	
10/05/15	2334	(b) (6)	WORLD HE TEMP WINDS 108°F, PROBE NEEDS TO BE RETRIEVED PRIOR TO NEXT FLIGHT. FURTHER CHECK 98.7% ADDDED THE REST OF HELIUM TUBE 2 FROM SHD 451.5. APPROX 500FT. 6000LBS	19152	50 JESIA/52780000 STR 5580 (3382 161)
10/15/15	1515		AS PER FROM FSA. ADDED TWO TUBES (4 AND 5) FROM SHD 451.5. LIFT A 32192 LBS.	19452	
10/15/15	1547		TRANSISTOR HE TEMP SENSOR. NEEDS TO BE RECALLED PN: 3D14071	21002	50 JESIA/52780000 STR 5580
10/15/15	1700				

Date	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10-2-15 2030			Replaced Temp Sensor Assembly (Hc) P/N 3D14 071 (ex.01 Component check is good.)	50/ 305A/327800005 SF/R 55800 000302 6/3	
10/4/15 0700			Unlocked 3.5 mins at 100' estimated limit now 3/1000 45° will create cross neutral position, no flight @ this time due to unstable short duration winds.		12402
10/4/15 0700			BEST WORST BEWON LOSS - ALL SYSTEMS GREEN/POWER REMOVED		13002
10/4/15 2055		(b)(6)	Launch on station. Cp 11345 / Wind 15 kts / Temp 45.3 Altitude 7696 ft Unlatch time was 2018 Airborne lft check = 20,442 at 7696' Winds 11.kt Temp 52.9°	005 514/5	
10-4-15 2235			Lubed rotary driver with Gear Shield grease.	023 5210/5	
10-5-15 0500			Tether move to 7899' / Cp 12230 / winds 18.7 kts / Temp 53.8 F	0802	
10-5-15 0515			bait entry. After launch blower #2 alarm came on. Suspect fitting/blower/cable issue. Parts ordered for trouble shooting and to be delivered to site	10/305A/32780001 SF/R 6119 22	
10-5-15 1900			E-Tac inspected Nose latches junction boxes and found the wipers to be dry and void of corrosion. Tech then sealed box. Inspection of lower box revealed water in box and corrosion on bus bar. Bus bar and new terminal ends ordered.	23002	

Page closed by (QA): [REDACTED] (b)(6)

Date: 10/6/15

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR# or N/A	Defect# or N/A
10/5/15	2200		Tether move to 8549' / CP 11917 / winds 16.5 Kts / Temp 49.0°F Time off move 2118L	012002 14/6	
10/6/15	0500		Tether Move 8760' / CP 12459 / winds 22.8 Kts / Temp 49°F 07002		
10/6/15	1255		TETHER MOVE TO 10,000' / CP 12,915 / WINDS 19.9 KTS / TEMP 58.1°F 16552		
10-6-15 0210D			Tether move to 9775' / CP 13163 / winds 15.5 Kts / Temp 45.7°F Scheduled move	0100210/7	
10/7/15	0500		Tether move to 9362' / CP 12916 / winds 25. Kts / Temp 45.2°F 09002		
10-7-15 130			(b) Took hydraulic fluid samples from all HPUs. SUGGEST DRAWING BOTTLE HPU AND FLUSHING IT TO REMOVE ALL WATER FROM THIS SYSTEM... ASAR!!	15302	
10-7-15 1241			TETHER MOVE TO 9750'. CP 13500 / WINDS 15.8 KTS / TEMP 46.0°F 16412		
10/7/15	2100		Tether moves to 9200' / CP 12,576 / wind 23.7 Kts / temp 41.2°F x 11/02 0100210/8		
10/8/15	0500		total move to 9000' / CP 12,576 / wind 27.5 Kts 09062		
10-8-15 1015			Recovered Flight ⁶¹⁹ for Army Training AT 0830. Inspected Netting Line Due to damage. Damage was 5% of the way up the line, requiring replacement.	10/8/15 083009	14152

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
			(CONTINUED) REPORT NOW REPAVED NOSE LATCH. ARMY STILL WANTS TO TRAIN, SO WORK WILL START ON JS 308 ONCE AEROSTAT IS PARKED AT MISSION ALTITUDE.	JG/JES 152730009 STR/JS 82	
10/8/15	1306		ARMY BEGAN TRAINING. FLIGHT 620 LAUNCHED AT 1305. UP/DOWNS WILL CONSIST OF FLIGHTS FROM POINT TO TAGLINE SEPARATION, THEN BACK DOWN.	17052	
10/8/15	1407		AEROSTAT REACHED MISSION ALTITUDE OF 8502' / CP 12,954 / WINDS 16.2 KTS / TCAP 55.7F. ARMY FD WENT FROM POINT DIRECTLY TO MISSION ALTITUDE AFTER 1 UP/DOWN. NO MOORING OCCURRED. STILL FLIGHT 620. (b)(6)	18072	
10/8/15	2140		RETURN MOORING 8499' TD / CP 13,321 / WIND 26.8 / TCAP 43.6° F	0142	1409
10/9/15	0500		E-TECH REPLACED CORRODED TERMINAL BLOCK INSIDE NOSE LATCH LOWER JUNCTION BOX. UPON COMPLETION, E-TECH SEALED BOLT HOLES IN THE COVER AS WELL AS LAIN A BEAD OF SEALANT AROUND THE ENTIRE COVER STR/JS 83 GASKET IN ATTEMPT TO RESTORE WATERTIGHT INTEGRITY OF THE JUNCTION BOX AND PREVENT FURTHER CORROSION RELATED ISSUES. STATUS OF NOSE LATCH INDICATOR WILL BE DETERMINED UPON RECOVERY AND MOORING OF FLIGHT 620.	14002	STR/JS 83

Page closed by (QA) _____ Date: 10/9/15

(b)(6) _____ Date: 10/9/15

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10/9/15	12:34		TETHER MOVE TO 5,212' DUE TO POTENTIALLY UNBOUND STORMCELL. CP 14,441 / WINDS 28.7 KTS / TEMP 63.1°F	16802	20242
10/9/15	16:34		RECOVERED FLIGHT 626 DUE TO THREAT OF IMMINENT LIGHTNING STRIKES IN THE AREA. UPON MOORING INTO THE NOSE LATCH, TELEMETRY DISPLAYED ALL THREE LATCH INDICATORS. APPROXIMATELY TEN MINUTES LATER THE "PROX" INDICATOR EXTINGUISHED. TROUBLESHOOTING WILL CONTINUE.		
10/10/15	16:22	(b)(6)	NO OUT ADJUSTING FROM ANNUAL RECORD TO DISCONTINUED FITBOL w/STORM IN THIS AREA, TO "UNARMED" IT. THIS IS NOT A GOOD PROOF OF IF KITS IS BOTH PROOFED AND THIS MEANS - ADVISED THAT THIS SHOULD NOT BE USED.	20242	00452 10/10
10/10/15	20:45		ANNUAL WAS UNARMED TO RECOMMEND FITBOL, MAST + STORM CACC'D OVER AND FITBOL SET PROBABLY TELEMETRY RECORD. FIBER AND KITS UNARMED FROM POSITION.		20242 00452 10/10
10/10/15	22:00		LAUNCHING TCOM FOR 621 & 21:38, SOUNDS TO POWER 100 CONE CIRCUIT HULLS ON J-MIC BEET-CHEM SHIELD AND A1 AND OUT OF COMD CELL; CAPTION WIRE MAINTS TO INC REPAID AND POSSIBLY WAD CASE AS WELL DIAZOD DIAZET OX W5,722740.		20242 10/10

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR# or N/A	Defect# or N/A
10/11/15	1430 ^s		E-TECH's TONY AND CASEY UNINSTALLED DAMAGED LOAD CELL (SN: 1293383) AND LOAD CELL CABLE (4P01255G01) AND INSTALLED THE LOAD CELL (SN: 1279947) AND LOAD CELL CABLE FROM SYSTEM 2. OPERATIONAL TEST SATISFACTORY.	J01JES9528400007 STD/ 5581 L0302	
10/11/15 0000			Launched Flight 622 AT 1537. LIFT: 30800085	20002	
10-11-15 0632			REACHED ALT 9999' TETHER DEPLOYED 17.1 KTS / 46.5° / 12,950 CP NOTCHED ON OUTBOARD DINK RATE @ 6008'. HAD WIND STOP OUTBOARD, REMOVED TAC TO INSPECT. FOUND NO ISSUES.	20322	
10/12/15 0452		(b)(6)	IN REGARDS TO THE LOG ENTRY ON 10/9/15 AT 1634, SHORTLY AFTER THE ISSUE WITH THE PROX LIGHT WAS LOGGED, THE INDICATOR RE-LIT AND ALL THREE INDICATORS REMAINED LIT UNTIL THE LAUNCH OF FLIGHT 622. ALSO, THE BLOWER #2 ISSUE LOGGED ON 10/9/15 SEEMS TO HAVE BEEN A MOISTURE ISSUE, AS IT HAS NOT REOCCURRED SINCE. WE WILL BE RETURNING ALL ASSOCIATED PARTS THAT WERE ISSUED BACK TO THE WAREHOUSE.	18522	
10/12/15 1656 ^s			TETHER MOVE TO 9700' CP 13772 / WINDS 24.5 KTS / TEMP 52.5°F last tether log move was at 11.56 pm (23.56)	20002	
10/13/15 0605			Tether move to 4818' / CP 1345416 / Temp 58°F / Winds 24 Kts	10052	
10/13/15 0650					10502

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10/13/15	10A00		hatched at 0826 Ending Flight 622 1224 unlatched at 0932 For Cert Flight 623	14422	
10/13/15	10A44		hatched at 1015 To End Cert Flight 623	14452	
10/13/15	10A45		Put Raytheon in Wind screen to work on payload	15342	
10/13/15	1134		Took Raytheon out of Wind screen at 1400	18002	
10/13/15	1400		Power went out of 1345 Gen's Kicked on host 60 Hz to moring system	18052	
10/13/15	1405			22592	14/3
10/14/15	0000	(b)(6)	Wrote monthly was on site TCOM EFT 624 unlaunched 14:55 am on 10/13. No room appears on site due to 460 Hz loss of GP. During our have him to throw 150 lbs bag and about 100 lbs with the other 100 was spares one them. TCOM crew lost GP to Assess the situation. When in question are normal no issues out HADL comt to 200 M. C. 8230 we make from some reason. Better Depressed now need TPC TPC indications comp. This will be caused failure on cert/bal/ctrl will though start upon next powerup. Also if note CP toward come to Faux Evidu now w/ GQ land case and status.	08002	

Date	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10/19/15	1204		Tether More to 7503	16042	
10/19/15	1305		Began in-haul of tether for Cert flights hatched at 1116 to end flight 624.	16052	
10/19/15	1215		Army started during preflight unlatched at 1235 to start cert flight 625	16052	
10/19/15	1305		hatched at 1300 ending cert flight 625	17052	
10-14-15	1418	(b)(6)	Mil Air arrived on site to change out faulty twin compressor relay switch. Unit changed out and tested 40. Rep also found ECU low on Freon and filled.	18202	
10-14-15	1755		Launched Team Flt 624 at 1748L for Army test flt recovered Team flt 624 at 1805L Flt time 1.26 hrs Total flt time = 7051.69 T+1 Apg + time = 744.13	21552	
10/19/15	2026		Tech's called TPIU for H2O on TIEOW - Rock bottom DUSTY MOUNTAIN observed in lines on site FAI Army prior we informed to GROOBARD PROBLEMS, THE FORM ADDITIONAL INSPECTIONS BUT HERMETIC NDOP-SURFACE NOT POSSIBLE.	20262	10/15
10/19/15	2036		Landed Team Flt 627 to 8326m / 13145 / 27000ft / 25.90° LIFT U 36, 712 - 854	02362	10/15

Page closed by (QA): _____

Date: _____

Page - 51 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H483026)	STR # or N/A	Date or N/A
01/15 9:30			Tensioner on bell screw was making some clunking noise. Took off cover and it appears to be wires aligned to the left. Tried realigning but I don't feel comfortable adjusting the tensioner/mid flight.	STR 5993	
1/15/09			RECONIZED TCOM EIT 627 & CH 23466 - PLATFORM GOOD Army 44000 TO 0200P KITS 08:00	08512	
1/15/09			Inspected Level wind tension spakket and found spakket teeth fitting on inboard chain link. Reset set collar to allow chain move off chain link and center will observe during next tether movement to ensure adjustment worked Start time 0655 End time 0715	STR 5993	11052
1/15/09			During start of shift noted HECH fault alarm. Upon inspection noted that HECH switch on LTA panel was "off" position. Need to remind Army that for HECH to work must be "on" position. Once in "on" position fault cleared. Start time 0750 end time 0800	1200Z	
1/15/09			Inspected Nose latch due to Nose latch abera. When moved LTP 5990 and in "neutral" position alarm illuminated. When nose attitude changes - or + light goes out. Adjusted nose "probe" latches sensor while probed and light goes out however light illuminates after several minutes. Need to further investigate Nose latch sensor	1210Z	

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10-15-15	1100		Launched TCOM, flt leg 8 at 1048L L.SA check -31,087 Climbed to 8000' level wind spraket tensioner still makes occasional "pop + clicks" will further investigate	STR 5593	15002
10-15-15	1155		R/R HWS top hatch gus strut. Install hel. calls on upper attachment bracket of hatch. Check 4.0 Start time 1125 End time 1155	STR 5592	15002
10/15/15	1420		TEETHER MOVE TO 5999' / CP 13,905 / WINDS 21.4 KTS / TEMP 50°F LATE ENTRY.	18202	
10/15/15	2228		TEETHER MOVE TO 6251' / CP 16,105 / WINDS 37.7 KTS / TEMP 37.9°F	02202 (9/16)	
10/16/15	0400	(b)(6)	TEETHER MOVE TO 6500' / CP 16,676 / WINDS 42.3 KTS / TEMP 43.7°F	08002	
10/16/15 0914			Teether move to 9202' / CP 15037 / winds 37.7 KTS / Temp 35 0°F	13142	
10/16/15 0917			late entry for 10-15-15 went up tower at 1500 to hook at center pt 500'. Sensor it looks messed up on the end so it need to be replaced (Drawing 3D16580 NHA) F/N 27 3 wire D/C inductive flex sensor part # 871C-DT G/N P12-4 & work lasted about 30 min's	open 10#	13172
10/16/15 1011			lost 60 Hz at 1000 here did hot 600sec 400 Hz	14112	

Page closed by (QA): _____ Date: _____

Page - 53 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10-10-17	10:00 AM	BLANK	BLANK	BLANK	BLANK

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10-16-15	1430		Completed prep for Mud Flush Unit. Added 60 gal. Requested another 55 gal to be delivered to site	18302	
10-16-15	1445		Received New Prox Sensors. Parts are on hand for install 10/17/15 AM	18452	
10-16-15	1445	(b)(6)	Tether move to determine line of Site minimum altitude with TDOC. Went down to 250' and back up to 900'. CP 14133' / Winds 29.5 Kts / Temp 27.7°F	18452	
10-16-15	1445		Received APCU Square (in high bay). Suspect bad APCU causing Emp failure alarms. Need to further troubleshoot	18452	
10-16-15	1530		A/B Humidity alarm illuminated. Steady on for minutes then goes out.	19302	
10/16/15	2300 ⁰⁰		TETHER MOVE TO 8750' / CP 14,085 / WINDS 33.3 KTS / TEMP 26.8°F	03002 10/17	
10/16/15	1440		BOTH MOTE TO 8494' AND 15294' AND 27.2 / TEND N/A INSTEAD TO SET OUT AT REACHING AND TWO BOTTOM CLOUD DBE IN <320F CONDITIONS AND TEND AND HE TEND ECOK WIDEN - ADMINISTRATIVE PROBLEMS CORRECTED TO CLOUD UP TO MOUNTAIN - WILL UPDATE THIO + CHT FEED H2O IN PROBLEMS USED CLOUD THIO + CHT (KIDS APPROVED AND DRAW TO 90%)	18402	

Page closed by (QA): _____

Date: _____

Page - 55 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10/17/15	2305		TETHER MOVE TO 5250' / CP 14,127 / WINDS 27.2 KTS / TEMP 31.1°F TETHER MOVE TO 9601 / CP 14436 / WIND 30.4 / TEMP 7-150(?) 1732	60152	
10/18/15	0003		ADVISED NMN! RD TO NMN - BALLOON IN CLOUDS TEMP 13°F ADVISED TO 5394' TD - CLEAR OF CLOUDS - 100% REVERSED IN AREA FROM CT - 7K ABOVE BE ABLE TO CONTINUE AFTER DART. (CLOUD SKY)	1732	
10/18/15	1802				
10/18/15	2320	(b)(6)			
10/18/15	2315		TETHER MOVE TO 5651' / CP 14454 / WINDS 31.4 KTS / TEMP 26.4°F	60152	1019
10/18/15	0550		TETHER MOVE TO 5900' / CP 14,981 / WINDS 27.6 KTS / TEMP 24.9°F	05002	
10/19/15	0921		Tether move to 1650'	13212	
10-19-15/1900			Replaced transverb CR43 (P/N. 15KP33) in FITSV #1 (S/N: MOO 2281).	23002	
			Replaced transverbs CR218 (P/N. 15KP130C) and CR186 - CR189 (P/N. 15KP220C) in FITSV #1 (S/N: MOO 2282). No issues. These units need to be installed upon next maintenance period to verify HCU circuit breakers no longer trip. Job order # 15282D004		
			Start time: 1400 End time: 1900		

15

(b)(6)

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10-01-15 1100 2100		(b)(6)	Started Flushing System at 1300. Successfully used compressed tank to blow out certain parts of system after heavy oil contaminated fluid started to leak up the flushing unit and realized we did not have necessary fittings. Re-connected system & refilled with hydraulic fluid, turned on HPV. System is still considered contaminated but will proper work during Inland for the time being. Ended at 2200.	17052 to 08002 10/2	
10-26-15 0153			Tether move 9999 ft / CP 12703 / Temp 40.7°F / Wind 25.5 Kts Tether move 9877 ft / CP 13,570 / Temp 41.2°F / Wind 12.1 Kts	05552 18302	
10/26/15 0700			Tether move 9997' / CP 12410 / Temp 47.7°F / winds 23.4 Kts	21302	
10/26/15 1730			Tether move to 9209' / CP 11757 / winds 1.3 Kts / Temp 44.2°F	0552	
10/27/15 0115		(b)(6)	Tether move 10000' / CP 13320 ^b / Temp 53.3 °F / Wind 19.1 Kts	13182	
10/27/15 0918			Tether move to 9849' / CP 13159 / winds 25.1 Kts / Temp 42.1 °F	21152	
10/27/15 1715			Tether move to 9244' / CP 11370 / winds 9.5 Kts / Temp 45.2 °F	05152	
10/27/15 0115			TETHER MOVE TO 9691' / CP 13,631 / WINDS 23.7 KTS / TEMP 53.4°F ARMY DOING QUARTERLY MAINTENANCE, WHICH INCLUDES TESTING E-STOPS WHILE OUTHAULING. ALL E-STOPS VERIFIED TO WORK CORRECTLY.	13152	

Page closed by (QA) _____ Date: 10/22/15

(b)(6) _____ Date: 10/22/15

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10/22/15	1811		Tether move 10000' / CP 160811b / Wind 91.2 Kts / Temp 47.7 °F		
10/22/15	2320		Changed gear o.1 in rotary driven 1+2 with 800-90 o.1 Used approx 5 qts. to for both drives combined Start 2045 Stop 2315	STR 5598	
10/23/15	0213	0815 OPNO	Tether move to 9819 ft / CP 1403516 / Temp 44.9 °F / Wind 35.2 Kts INSPECTED CAGE AND SHEAVES. BOTH LOOKED P. VS. AND ADJUSTED SWING S. BOTH SWING FREELY. INSPECTED ROPE LATCH. SHOWED SIGNS OF WEAR BUT NOT CRITICAL TO DOWNGRADE THIS NOSE 6.9K. YET. FURTHER WORK MIGHT BE NEEDED AS MORE FEET/ITS ARE LAUNCHED/REMOVED. Start: Stop:		
10/23/15	1004		TETHER MOVE TO 9494' / CP 13164 / WINDS 30.4 KTS / TEMP 47.6°F		
10/23/15	1810		Tether move to 9494' / CP 12833 / winds 35.0 Kts / Temp 47.2 °F		
10/24/15	0214		Tether move to 9200' / CP 11172 / winds 9.8 Kts / Temp 46.7 °F		
10/24/15	1006		TETHER MOVE TO 9691' / CP 13396 / WINDS 9.6 KTS / TEMP 58.3°F REMOVED RUSTY CAGE SHEAVES AND REPLACED BEARINGS. REINSTALLED SHEAVES. NO ISSUES.		
10/24/15	1500		(b) (6)		

Page - 58 -

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defectif or N/A
10-24-15	1707	[REDACTED]	Tether move at (1654) to 9249' /cp 13520 /wind 22.5 Kts /Temp 52.5 °F		
10-24-15	2200	[REDACTED]	System pitched to 32.3° Waels windscreen inspection on next recovery		
10-25-15	0300	[REDACTED]	Tether move to 8999' /cp 13140 /winds 20.4 Kts /Temp 49.7 °F		
10-25-15	1020	[REDACTED]	Tether move to 9299' /cp 14410 /winds 35.9 Kts /Temp 42.0 °F		
10-25-15	1350	[REDACTED]	Conducted several tests to troubleshoot the OTH 107 alarms. Found that walets beacon 3 and 4 are commanded on, thus open and check valves 3 and 4. Thus alarm is no longer displayed. It might be beneficial to inspect the bellows and pressure diots to ensure they are not restricted preventing air flow to empenage tanks or aerostat. Start — Stop —		
10-25-15	1450	[REDACTED]	Completed all PMs except for the noise latch. The noise latch card not be completed due to the alarm on board.		
10-26-15	0100	[REDACTED]	Tether move to 9541' /cp 13067 /winds 17.3 Kts /Temp 38.7 °F		
10-26-15	0105	[REDACTED]	Tether move to 9260' /cp 13700 /winds 29.6 Kts /Temp 42.0 °F		
10-26-15	0900	[REDACTED]	Tether move to 9326' /cp 14115 /winds 24.7 Kts /Temp 35.0 °F		

Page - 59.

Page closed by (QA) _____

(b)(6) _____ Date 10/27/15

Date of Entry	Time of Entry	Entry by	Description of work, affected part identification, etc. (reference procedure H463028)	STR # or N/A	Defect# or N/A
10-21-15 1045			TETHER MOVE 8899' / CP 12483 / WINDS 9.4 KTS / TEMP 38.9°F		
10-27-15 0650			Tether move to 8649' / CP 11563 / winds 8.4 Kts / Temp 39.5°F		
10/21/15 0948			TETHER MOVE TO 9999' / CP 12,131 / WINDS 10.2 KTS / TEMP 38.3°F		
10/21/15 1615		(b) (6)	TETHER MOVE TO 7998' / CP 13,393 / WINDS 10.4 KTS / TEMP 48.8°F Tether Move to 6506' / CP 14451 / Winds 30.5 Kts / Temp 45.3°F TOTAL MOVE TO 6502' / CP 6104 / WIND 38.3 / TEMP 46.0°F		
10/21/15 2045			AT APPROX 11:30 we TETHER FAILED IN TERRAIN - WORKED TO SOURCE. SIGNIFICANT DAMAGE TO MOUNTING AREA AND COMPOUNDS ON THIS MTS		
10/22/15 0100					
10/22/15 1620					

Page - 59

000180

EPIIC-16-02-23-Army-FOIA-20170606-Blimp-Report

epic.org

EQUIPMENT INSPECTION AND MAINTENANCE WORKSHEET

For use of this form, see DA PAM 750-8; the proponent agency is DCS, G-4.

1. ORGANIZATION A-3RD ADA (JLENS)			2. NOMENCLATURE AND MODEL MOBILE MOORING STATION (MMS)			
3. REGISTRATION/SERIAL/NSN 0002	4a. MILES	b. HOURS	c. ROUNDS FIRED	d. HOT STARTS	5. DATE 22 OCT 15	6. TYPE INSPECTION Quarterly
7. APPLICABLE REFERENCE						
TM NUMBER JLENS-A-M0-60-0000-00A-300A-A		TM DATE 20141205		TM NUMBER JLENS-A-M0-60-0001-00A-300A-A		TM DATE 20141205
COLUMN a - Enter TM item number. COLUMN b - Enter the applicable condition status symbol. COLUMN c - Enter deficiencies and shortcomings.			COLUMN d - Show corrective action for deficiency or shortcoming listed in Column c. COLUMN e - Individual ascertaining completed corrective action initial in this column.			
STATUS SYMBOLS						
"X" - Indicates a deficiency in the equipment that places it in an inoperable status.			DIAGONAL "(/)" - Indicates a material defect other than a deficiency which must be corrected to increase efficiency or to make the item completely serviceable.			
CIRCLED "X" - Indicates a deficiency, however, the equipment may be operated under specific limitations as directed by higher authority or as prescribed locally, until corrective action can be accomplished.			LAST NAME INITIAL IN BLACK, BLUE-BLACK INK, OR PENCIL - Indicates that a completely satisfactory condition exists.			
HORIZONTAL DASH "(-)" - Indicates that a required inspection, component replacement, maintenance operation check, or test flight is due but has not been accomplished, or an overdue MWO has not been accomplished.			FOR AIRCRAFT - Status symbols will be recorded in red.			
ALL INSPECTIONS AND EQUIPMENT CONDITIONS RECORDED ON THIS FORM HAVE BEEN DETERMINED IN ACCORDANCE WITH DIAGNOSTIC PROCEDURES AND STANDARDS IN THE TM CITED HEREON.						
8a. SIGNATURE (Personnel performing inspection) SSG (b)(6)	8b. TIME 0800Z TEK 1840E	9a. SIGNATURE (Maintenance Supervisor) SFC (b)(6)	9b. TIME 2314Z	10. MANHOURS REQUIRED		
TM ITEM NO. a	STATUS b	DEFICIENCIES AND SHORTCOMINGS c	CORRECTIVE ACTION d			INITIAL WHEN CORRECTED e
20		HPUs: With the HPUs off, exercise all the HPU change over panel valve handles. Turn each handle several times ensuring complete freedom of movement. Return handles to original position when complete.	Exercised all handles			(b)(6)
27		CAPSTAN: Lubricate the upper capstan drum load sensing sheave and idler sheave. Lubricate the upper and lower capstan drum pillow block bearings, high and low tension sheaves, and the high and low tension idler sheave.	LUBRICATED			(b)(6)
55		MOORING TOWER AND SAFETY RAILS: Inspect all placards for legibility	checked all rails and placards			(b)(6)
56		GROUNDING SYSTEM: Visually inspect grounding ring for cracks, damage or corrosion	inspected			
57		Visually inspect all copper wire connections for corrosion	inspected			
66		ROTARY DRIVE DAMPENING DEVICE: Inspect for hydraulic leaks, loose or missing hardware	inspected			
68		MACHINERY ENCLOSURE CENTRAL BEARING: Lubricate MEC bearing	Team Shawn Mountain Inspected			
69		NOSE LINE WINCH/CLOSE HAUL WINCH APU EMERGENCY STOP BUTTON: Energize	Emergency stops operated for			
		HPU: Operate winch control lever in inhaul/outhaul. have NLW/CHW operator press the emergency stop button. Verify control lever does not operate winch in inhaul/outhaul mode. Reset winch.	NLW/CHW . E-SAFES OPERATED			
			correctly			

EQUIPMENT INSPECTION AND MAINTENANCE WORKSHEET

For use of this form, see DA PAM 750-8; the proponent agency is DCS, G-4.

1. ORGANIZATION A-3RD ADA (JLENS)			2. NOMENCLATURE AND MODEL MOBILE MOORING STATION (MMS)			
3. REGISTRATION/SERIAL/NSN 0002	4a. MILES	4b. HOURS	c. ROUNDS FIRED	d. HOT STARTS	e. DATE	f. TYPE INSPECTION Monthly
7. APPLICABLE REFERENCE						
TM NUMBER JLENS-A-M0-60-0000-00A-300A-A		TM DATE 20141205		TM NUMBER JLENS-A-M0-60-0001-00A-300A-A		TM DATE 20141205
COLUMN a - Enter TM item number. COLUMN b - Enter the applicable condition status symbol. COLUMN c - Enter deficiencies and shortcomings.			COLUMN d - Show corrective action for deficiency or shortcoming listed in Column c. COLUMN e - Individual ascertaining completed corrective action initial in this column.			
STATUS SYMBOLS						
"X" - Indicates a deficiency in the equipment that places it in an inoperable status.			DIAGONAL "(/)" - Indicates a material defect other than a deficiency which must be corrected to increase efficiency or to make the item completely serviceable.			
CIRCLED "X" - Indicates a deficiency, however, the equipment may be operated under specific limitations as directed by higher authority or as prescribed locally, until corrective action can be accomplished.			LAST NAME INITIAL IN BLACK, BLUE-BLACK INK, OR PENCIL - Indicates that a completely satisfactory condition exists.			
HORIZONTAL DASH "(-)" - Indicates that a required inspection, component replacement, maintenance operation check, or test flight is due but has not been accomplished, or an overdue MWO has not been accomplished.			FOR AIRCRAFT - Status symbols will be recorded in red.			
ALL INSPECTIONS AND EQUIPMENT CONDITIONS RECORDED ON THIS FORM HAVE BEEN DETERMINED IN ACCORDANCE WITH DIAGNOSTIC PROCEDURES AND STANDARDS IN THE TM CITED HEREON.						
8a. SIGNATURE (Person(s) performing inspection) SSG	(b)(6)	8b. TIME 1919	9a. SIGNATURE (Maintenance Supervisor) SPC	9b. TIME 2314Z	10. MANHOURS REQUIRED	
TM ITEM NO. a	STATUS b	DEFICIENCIES AND SHORTCOMINGS c		CORRECTIVE ACTION d		INITIAL WHEN CORRECTED e
1		INTERIOR: Inspect the interior of the machinery enclosure for cleanliness and remove any FOD		free of FOD		(b)(6)
2		Inspect the LTA/LC plumbing and all hydraulic lines, bulkhead fittings, and filters for leaks or damage		no damage		
3		Check that all fire extinguishers are fully charged		fully charged		
4		Inspect the ecu vents and filters for cleanliness. replace filters if necessary		inspected		
6		Check the interior for damaged, peeling paint, damaged insulation, corrosion, and water leaks		no damage		
7		EXTERIOR: inspect the 60 hz transformer and electrical cable for proper connection. Check for wear or damage to the electrical cable insulation		checked		
9		Inspect the outriggers, cribbing, and all hardware for security and corrosion. ensure all cribbing are seated properly /cannot be moved.		checked		
10		Check the tie downs and anchors on the outriggers for security. inspect for loose or missing hardware, corrosion control and care paint for surface condition. clean as required		checked		
11		Check the LTA/LC and ECU air intakes for cleanliness. Clean and remove FOD, mud or dust		checked		
		inspect the LTA/LC sight glasses to verify coolant levels are at proper operating levels. Check the sealant integrity				

ITEM NO. a	STATUS b	DEFICIENCIES AND SHORTCOMINGS c	CORRECTIVE ACTION d	INITIAL WHEN CORRECTED e
40		BOOM ASSEMBLY: inspect working surfaces for cleanliness	inspected	(b)(6)
41		Inspect all boom work platforms, support struts, and hardware for damage, corrosion, and missing hardware. Ensure all struts are properly pinned and secure	inspected	
42		Check flying sheave springs for damaged and functionality.	checked	
43		Inspect security of safety rails, 'J' rails, and work platform	inspected	
44		FLYING SHEAVE: Inspect for freedom of movement		
46		CLOSE HAUL WINCHES: inspect for hydraulic leaks	inspected	
47		Inspect CHW sheaves for freedom of movement	inspected	
48		Inspect spreader beam assemblies for security and corrosion	checked	(b)(6)
50		Inspect all placards for legibility	checked	
51		CHW HPU: Inspect hydraulic fluid through sight glass, fill as necessary	inspected	
52		Inspect for hydraulic leaks, loose or missing hardware	no leaks	
53		Inspect seals for wear, tearing and dry-rot	no wear/tear	
54		MOORING TOWER and SAFETY RAILS: inspect railings, safety chains, and the ladder for loose or missing hardware, corrosion or damage.	inspected	
121		AEROSTAT ASSEMBLY: Forward and aft close haul lines inspection		
127		MMS INTERIOR: Inspect lighting control panel for functionality.	functional	
128		Inspect machinery environmental control unit control panel	MECU CP functional	
129		CLOSE HAUL WINCHES: Move centering springs back and forth to ensure springs work properly.	FMC	
		Inspect centering springs for damage.		
130		MMS EXTERIOR: Inspect electrical cable insulation along length from 60hz pedestal transformer to machinery enclosure for wear and damage.	No wear/damage	(b)(6)
133		MMS INTERIOR: Inspect interior (siding, doors, louvers, etc.) for damage, peeling paint, corrosion, and water leaks	inspected	
134		Visually inspect tether storage drum ECU cooling fan outlet for cleanliness and indications of damage.	checked	
135		Visually inspect capstan ECU cooling fan outlet for cleanliness and indications of damage.	checked	
138		MMS EXTERIOR: Inspect main access door latches and access ladder for damage and deterioration	checked	
		Lubricate door hinges and latches with oil		

TM ITEM NO. <i>a</i>	STATUS <i>b</i>	DEFICIENCIES AND SHORTCOMINGS <i>c</i>	CORRECTIVE ACTION <i>d</i>	INITIAL WHEN CORRECTED <i>e</i>
140		Check enclosure exterior for damage, peeling paint, and corrosion. repair as required.	checked	
141		Inspect sealant at fitting joints and fastener heads. ensure that hardware is complete and secure.	inspected	
144		Inspect all railing mounting brackets. Ensure that all hardware is present and secure.	inspected	
145		Inspect hydraulic hoses and filters for leaks. Clean as required.	inspected	
146		Observe sight glass on reservoir inside of boom HPU enclosure and annotate fluid level.	checked	(b)(6)
147		Observe sight glass on reservoir inside tower HPU and annotate fluid level.	checked	
148		Inspect boom HPU filter, any accessible hoses, and floor of HPU enclosure for fluid leaks.	checked	
149		Inspect tower HPU filter, any accessible hoses, and floor of HPU enclosure for fluid leaks.	checked	
154		TETHER WINCH HPU: Perform a spectroanalysis check by draining 4 to 8 fluid ounces of hydraulic fluid into a clean container that can be sealed. submit fluid sample for analysis if sample is contaminated. contact contractor logistics support (cls)		
155		Exercise eight valve handles on tether HPU change over panel. Rotate handles 1 through 5 to drive 2 position. Starting with handle 1. Exercise handle a minimum of three times returning handle to normal position when exercise has been completed	exercised	(b)(6)
156		Exercise three red valve handles on tether HPU change over panel a minimum of three times returning handles to normal position when exercise has been completed	exercised	
157		Inspect all hydraulic hoses and lines for chafing, wear, kinking or dry rot.	inspected	
160		CAPSTAN: Inspect hydraulic motor mounting hardware for security and corrosion.	inspected	
161		Inspect lower and upper drum bearing mounts for security and corrosion.	inspected	
162		TETHER: Inspect boom assembly tether from brush seal to flying sheave for nicks.	checked	
168		WOCC: Replace ECU filter if filter is damaged or cannot be cleaned sufficiently to allow air flow.	inspected	
169		TOWER HPU: perform a spectroanalysis check by draining 4 to 8 fluid ounces of hydraulic fluid into a clean container that can be sealed. Submit fluid sample for analysis.		
171		BOOM ASSEMBLY: Inspect AWP mounting hardware for corrosion, damage, or missing hardware.	inspected	
172		Inspect tag lines for wear and chafing.	checked	
173		AWP: Perform function checks and routine inspections and lubrication IAW TM		
178		LTA/LC and MECU: Inspect for coolant fluid leaks. tighten tubing and piping as required leading to LTA/LC, MECU #1 and MECU #2	INSPECTED AND LUBRICATED inspected	

TM ITEM NO. a	STATUS b	DEFICIENCIES AND SHORTCOMINGS c	CORRECTIVE ACTION d	INITIAL WHEN CORRECTED e
12		Inspect the integrity of the ita/lc and ecu mounting brackets; inspect the locking hardware on ecu NBC filters for security and proper sealing. inspect the nbc blower located on boom for security and cleanliness	checked	
13		Inspect the main access door, top hatch,occ door, and all access ladders for damage. ensure the ratchet straps on the boom end ladder are not loose and hold the ladder securely in place	no damage, secure	
14		Check the exterior for damage, peeling paint, corrosion and water leaks. leaks should be repaired	checked	
15		Inspect all safety railings and chains located on the mms enclosure, boom, and any work platforms	checked	
17		Verify that all the lighting stations operate	verified	
18		AWP: Inspect guide rails for FOD. Perform daily inspection recommended by AWP manufacturer	inspected	
		inspect AWP for side to side freedom of movement		
19		HPU: inspect the hpu reservoirs for leaks and proper fluid levels. add fluid if necessary.	fluid level in spec	
21		CAPSTAN: Inspect for hydraulic lines for leaks, chafing or kinking	no leaks	
24		Inspect the load cell cable for security	secure	
25		Visually inspect the capstan drums mounting hardware for security	inspected	
26		With the HPUs off, exercise capstan emergency panel change over valves ensuring freedom of movement. also check that the gauges read "0" and that the break: release pump handle is secure.	exercised all handles	(b)(6)
29		TETHER STORAGE DRUM: Inspect for hydraulic leaks	no leaks	
30		Visually inspect level wind for correct alignment . inspect the rollers on fleet angle rocker for damage and wear. Check that the shoulder screw holding the fleet angle rocker to the level wind is not damaged	inspected	
33		WINCH OPERATOR CONTROL CAB: inspect the console for cleanliness; clean all windows and sky dome mirror and if necessary, the telemetry display screens.	WOLC Serviceable	
34		Perform function check on control levers and perform lamp test to ensure functionality of control panel lights	checked	
35		Inspect TDS display screens for functionality and damage. Ensure that the screens dimmer switches function correctly/that the screens return to full brightness.	fully functional	
36		NOSE LINE WINCH/HPU: Inspect hydraulic lines for chafing, leaks, or dry rot	checked	
37		Visually inspect winch hydraulic fluid reservoir level using the sight glass on the reservoir	checked	
39		BOOM ASSEMBLY: Visually inspect all hydraulic and LTA/LC hoses and piping for leaks, kinks or damage	inspected	



REPLY TO

**DEPARTMENT OF THE ARMY
UNITED STATES ARMY COMBAT READINESS CENTER
FORT RUCKER, ALABAMA 36362-5363**

CSSC-O

23 November 2015

MEMORANDUM FOR Commander [REDACTED] (b)(3)
Aberdeen Proving Grounds, Maryland

SUBJECT: Release of Aerostat site and materials

1. Aerostat, SN 74M002, the associated MMS, all related mission equipment, and personal items associated with CRC Case # 201510281147X74M002 is released to the Commander, [REDACTED] (b)(3) for final disposition pending release by the collateral officer.

2. The United States Combat Readiness Center point of contact is CW4 [REDACTED] (b)(6) at DSN [REDACTED] (b)(6) Com [REDACTED] (b)(6) and email [REDACTED] (b)(6)

[REDACTED]
(b)(6)

MAJ, AV
Board President