



SERVICE BULLETIN

Service and Maintenance manual N° ALL

Bulletin N° 009/Oct/11

Equipment affected:

All ISP manufactured products including Lifejackets and Bladder Assemblies fitted with the **Hammar Inflation Units only**.

Reason for issue:

Notification of Safety Information issued by the Manufacturer of **Hammar Inflators**. This Service Bulletin and Safety Alert reiterates the previous Service Bulletin (No' 002/Jan/09) issued at the beginning of 2009 following a similar Safety Notice issued by *CM Hammar AB* .

Materiel required:

N/A

This bulletin is effective:

From: Immediate
To: Until Further Notice

Instruction:

Please can you review (and circulate as deemed appropriate to all service personnel) and take appropriate actions as described in the Safety Alert issued by **CM Hammar AB** (appended on page 2 of this bulletin) to our industry.

Authorised by Name (print) : Paul Houghton

Position : Technical Manager

Signature :

Date : 14th October 2011

All queries relating to this Service bulletin should be addressed to: Technical Dept,
International Safety Products L^{td}. Orrell mount, 159 Hawthorne Road, Bootle, Merseyside. L20 6JU. U.K.

Telephone: +44 (0)151 922 2202

Facsimile: +44 (0)151 922 5874



2011-09-08

Press release:

SAFETY ALERT – Inflatable lifejackets equipped with Hammar Hydrostatic Inflator manufactured before 2006

This Safety Alert was recently distributed to shipping authorities and advertised in the trade press, boating magazines and digital media worldwide.

The Hammar Hydrostatic Inflator is attached to the lifejacket with a sealing ring. In 2006, CM Hammar upgraded the sealing ring with new state of the art raw materials, to eliminate potential defects and increase long term durability. A small number of sealing rings manufactured before 2006 have suffered premature material degradation, most likely after being exposed to extreme environmental conditions. When exposed to high temperature and high humidity for a long period of time, the sealing ring might become stiffer, change colour and in severe cases cracking of the plastic may occur. The change does not occur overnight and can be detected at the recommended service or inspections.

CM Hammar are concerned that a damaged sealing ring might put the user at risk. **We recommend owners of lifejackets manufactured before 2006 that have not been serviced recently** to contact the nearest authorized service station for an annual service. The date of manufacture can be identified on the inside of the lifejacket cover. Owners who still want to do the check of the sealing ring themselves are advised to visit www.cmhammar.com/inflator for further information.

Lifejackets manufactured after 2006 are not affected by this Safety Alert.