

REPORT OF AIR FORCE AIRCRAFT ACCIDENT

(Fill in all applicable spaces. If additional space is desired, use additional sheets of paper and identify by section and item number)

1. GENERAL INFORMATION																																		
1. PLACE OF ACCIDENT (State, county, nearest town, or distance and direction from nearest town. If accident occurred on airport identify.) Texas, Glasscock Co, 19 NM SW of Sterling City, Texas; 15 NM SE of Garden City, Texas.																																		
2. DATE OF ACCIDENT		3. HOUR (Local)		4. TIME ZONE		5. PERIOD OF DAY		6. AIRFIELD OF LAST TAKEOFF																										
25 May 55		2300		CST		DAWN DAYLIGHT DUSK NIGHT <input checked="" type="checkbox"/>		Walker Air Force Base, Roswell, N.M.																										
7. CLEARANCE																																		
8. BASE SUBMITTING REPORT		9. DURATION OF FLIGHT		10. MISSION OF FLIGHT (Use DD Form 781-1 symbol)		11. ALTITUDE OF ACFT ABOVE TERRAIN IF COLLISION, FIRE AIRFRAME FAILURE, BAILOUT, SPIN, STALL. SPIRAL OCCURRED		12. AIRFIELD DATA																										
Walker AFB Roswell, N.M.		10:41		110H		25,000'		CLEARANCE FROM Roswell, N.M. CLEARANCE TO Roswell, N.M.																										
13. SERIAL NUMBERS OF ALL OTHER ACFT INVOLVED N/A																																		
14. VIOLATIONS (If yes, discuss in Sec XIID) <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO																																		
II. AIRCRAFT																																		
15. AIRCRAFT NUMBER			16. TYPE, MODEL, SERIES AND BLOCK NUMBER				17. ASGMT AND STATUS CODE AT TIME OF ACCIDENT (See AFR 65-110)																											
52-2818A			B-36J-5-CF				CC																											
18. ORGANIZATION POSSESSING AND REPORTING AIRCRAFT ON AF FORM 110 REPORTS AT TIME OF ACCIDENT																																		
MAJOR COMMAND		SUBCOMMAND		AIR DIVISION		WING		GROUP		SQUADRON OR UNIT		BASE																						
SAC SAC		15th AF 15		47th		6th		N/A		40th/311		Walker AFB																						
19. LOSING ORGANIZATION										IF AIRCRAFT WAS BEING FERRIED OR DELIVERED																								
N/A					N/A					N/A					N/A																			
III. PILOT(S) INVOLVED (Flight #)																																		
(If more than two pilots are involved (Flight crew) report same information required in item 21 on additional sheet for each)																																		
A. LAST NAME - FIRST NAME - MIDDLE NAME										GRADE		COMPONENT		SERVICE NUMBER		NATIONALITY		YEAR OF BIRTH																
Basinger, L. C. (I.O.) Jr.										Capt		AF		AO 754311		Caucasian		1920																
B. POSITION IN AIRCRAFT AT TIME OF ACCIDENT										C. ASSIGNED DUTY ON FLIGHT ORDER																								
<input checked="" type="checkbox"/> HEAD OF CABIN SEAT					<input type="checkbox"/> REAR OF CABIN SEAT					<input checked="" type="checkbox"/> AC					<input type="checkbox"/> IP					<input type="checkbox"/> P					<input type="checkbox"/> CP					OTHER (Specify)				
D. ASSIGNED ORGANIZATION										E. ATTACHED ORGANIZATION FOR FLYING																								
MAJOR COMD		SUBCOMMAND OR AF		AIR DIVISION		WING		GROUP		SQUADRON OR UNIT		BASE		MAJOR COMD		SUBCOMMAND OR AF		AIR DIVISION		WING		GROUP		SQUADRON OR UNIT		BASE								
SAC		15th AF		47th		6th		N/A		40th		Walker AFB		N/A		15th AF		47th		6th		N/A		40th		Walker AFB								
F. AERONAUTICAL RATING										G. INSTRUMENT CARD										H. AFSC														
OFFICIAL		DATE RECEIVED		PRESENT		DATE RECEIVED		TYPE		DATE OF EXPIRATION		PRIMARY		DUTY		OFFICIAL		DATE RECEIVED		PRESENT		DATE RECEIVED		TYPE		DATE OF EXPIRATION		PRIMARY		DUTY				
Pilot		30 Aug 43		Senior Pilot		4 Dec 50		Green		6 Mar 56		1234A		1234A		Pilot		11 Jun 54		Senior Pilot		11 Jun 54		Green		11 Feb 56		1234A		1234A				
A. LAST NAME - FIRST NAME - MIDDLE NAME										GRADE		COMPONENT		SERVICE NUMBER		NATIONALITY		YEAR OF BIRTH																
Bowman, Harold Vincent										Capt		AF		A0666123		Caucasian		1917																
B. POSITION IN AIRCRAFT AT TIME OF ACCIDENT										C. ASSIGNED DUTY ON FLIGHT ORDER																								
<input checked="" type="checkbox"/> HEAD OF CABIN SEAT					<input type="checkbox"/> REAR OF CABIN SEAT					<input checked="" type="checkbox"/> AC					<input type="checkbox"/> IP					<input type="checkbox"/> P					<input type="checkbox"/> CP					OTHER (Specify)				
D. ASSIGNED ORGANIZATION										E. ATTACHED ORGANIZATION FOR FLYING																								
MAJOR COMD		SUBCOMMAND OR AF		AIR DIVISION		WING		GROUP		SQUADRON OR UNIT		BASE		MAJOR COMD		SUBCOMMAND OR AF		AIR DIVISION		WING		GROUP		SQUADRON OR UNIT		BASE								
SAC		15th AF		47th		6th		N/A		40th		Walker AFB		N/A		15th AF		47th		6th		N/A		40th		Walker AFB								
F. AERONAUTICAL RATING										G. INSTRUMENT CARD										H. AFSC														
OFFICIAL		DATE RECEIVED		PRESENT		DATE RECEIVED		TYPE		DATE OF EXPIRATION		PRIMARY		DUTY		OFFICIAL		DATE RECEIVED		PRESENT		DATE RECEIVED		TYPE		DATE OF EXPIRATION		PRIMARY		DUTY				
Pilot		11 Jun 54		Senior Pilot		11 Jun 54		Green		11 Feb 56		1234A		1234A		Pilot		11 Jun 54		Senior Pilot		11 Jun 54		Green		11 Feb 56		1234A		1234A				

3-367
 52-2818A-105-10

PERSONNEL INVOLVED

Date at Time of Accident	Name (Last Name First, Grade, Serial Number & Service)	Type Aero Rating	Org. Assignment Command, Sub Com- mand, Group number Type and Base	Injury Class	Para- chute Used		Ejection Seat Used	
					Yes	No	Yes	No
47	Basinger, L. C. Jr. Captain AO-754311 USAF B	SR PLT	SAC; 15th AF; 6th Bomb Wg, (H); Walker AFB, Roswell, NMEX	Fatal 4		X		N/A
01	Bowman, Harold V. Capt AO-666128 USAF B	SR PLT	Same	Fatal 4		X		N/A
07	Morton, Ernest R. Capt AO-688975 USAF B	AOB *	Same	Fatal 4		X		N/A
08	Fred, Arthur R. Capt AO-2064559 USAF B	AOB *	Same	Fatal 4		X		N/A
08	Zalotka, Charles C. Captain AO-733573 USAF B	AOB *	Same	Fatal 4		X		N/A
13	Ensor, Nelson H. Capt AO-2101785 USAF B	AO(APE) ***	Same	Fatal 4		X		N/A
13	Glover, Richard B. 2/Lt AO-2024195 USAF B	AO(APE) ***	Same	Fatal 4		X		N/A
10	Cannon, Leonard T. T/Sgt AF-19253266 USAF A	RAF CPR ***	Same	Fatal 4		X		N/A
10	McNoil, Terance M. A/2C AF-13461639 USAF A	RAF CPR ***	Same	Fatal 4		X		N/A
11	Messer, David C. T/Sgt AF-14165059 USAF A	GUN ***	Same	Fatal 4		X		N/A
11	Davis, Charles J. T/Sgt AF-13327655 USAF A	GUN ***	Same	Fatal 4		X		N/A
11	Longley, Walter D. T/Sgt AF-11090513 USAF A	GUN ***	Same	Fatal 4		X		N/A
11	Davis, Charles L. A/1C AF-25940050 USAF A	GUN ***	Same	Fatal 4		X		N/A
11	Collings, Ernest J. Jr. AC AF-12180744 USAF A	GUN ***	Same	Fatal 4		X		N/A
11	Wardner, Billy A/1C AF-12180744 USAF A	Crew Chief ***	Same	Fatal 4		X		N/A

** - Crew Chief (not a Performance Engineer)
*** - Gunner

(15)

STATEMENT OF WEATHER OFFICER
Reference Section VI AF Form 114

The synoptic weather situation on the night of 25 May 1955 in the area of San Angelo, Texas and Big Spring, Texas was as follows:

A shallow low which had been centered over southwestern Utah at noon had intensified and moved to a position along the Texas-Oklahoma Panhandle border by midnight on the 25th. A dry cold front which had moved rapidly across New Mexico during the day accompanied by high westerly winds and dust reinforced a nonactive squall line which at 2000C had extended from Dodge City, Kansas, to Elk City, Oklahoma, to Wichita Falls, Texas to San Angelo, Texas, with the portion south of 20 miles north of Abilene, Texas, inactive until the reinforcement by the cold front. The air to the east of the front in Texas was moist and unstable while the air to the west was colder, dry and unstable.

The air throughout Texas had been unstable with considerable thunderstorm activity for two days prior to the accident. The stability index for Midland, Texas at 2100C on the 24th was minus 4, which had stabilized to plus 7 at 0800H on the 25th, with stability index of stations to the northeast all dropping to negative or small positive quantities.

At the time of the accident the ceilings were reported to be 8000 feet or above with lower scattered clouds at about 5000 feet at stations in the vicinity. Visibility was unrestricted except local blowing dust restricting visibility at Goodfellow AFB, Texas to 1/8 mile and Big Spring, Texas, restricting visibility to 10 miles in very light rain showers. Strong gusty surface winds were reported at all stations in the area with activation of the squall line.

Storm detection from Lubbeck, Midland, Big Spring, Abilene and San Angelo, Texas, indicated that as the colder dry air behind the front reinforced the inactive squall line, a large line of thunderstorms developed and built rapidly from small, isolated cells at 2100C to a continuous line of over two hundred miles in length at 2300C, and that this line moved in a generally easterly direction to 2330C. The width of the line during its strongest stages was 20 miles with hail reported by several witnesses in the Garden City and Sterling City area.

Samuel F. Freeland
SAMUEL F. FREELAND
Major USAF

SECTION XIII
AF Form 14
15 Dec 54

53. HISTORY OF FLIGHT:

Abbott 27 took off at 1219 CST, 25 May 1955, from Walker Air Force Base on a routine operational training mission, round robin, Walker AFB DRT Durant, Oklahoma DRT Greenville, Texas DRT Dallas, Texas DRT Oklahoma City, Oklahoma DRT Walker AFB, Roswell, New Mexico. The Form 175 indicated: Clearance VFR, sixteen hours plus thirty minutes of fuel and estimated time enroute eleven hours.

Abbott 27 proceeded to Oklahoma City via the route filed, arriving at 1632 CST. After completing bomb plot activity, Abbott 27 departed Oklahoma City, Oklahoma at 1815 on a changed clearance from VFR to IFR 1000 ft on top to Roswell via Waco and San Antonio, Texas. A position report was made over Fort Worth, Texas at 1905 CST and route change approved San Antonio, Texas via Kerrville, Texas. Upon arrival at San Antonio at 2015 CST, Abbott 27 was cleared on to bomb plot and accomplished two very successful RBS runs.

Abbott 27 then requested and was granted a clearance to proceed from over San Antonio, Texas direct to Walker AFB, Roswell, New Mexico IFR 1000 ft on top. The pilot reported on course at 2153 CST. The next radio contact Abbott 27 made was with San Angelo radio, reporting 18 nautical miles south at 2244 CST, 25,000 ft, IFR 1000 ft on top.

The last known radio contact with Abbott 27 was report of Hobbs and Roswell weather transmitted by San Angelo. This was approximately 2249 CST.

Abbott 27 crashed at coordinates $31^{\circ}41'45''N$ - $101^{\circ}20'00''W$ at approximately 2305 CST. The first report of the crash was telephoned by Mr. Charlie Davis, an eye witness of the crash, to the Sheriff's office at Sterling City, Texas just prior to 2310 CST. The crash occurred in the southwest corner of Glasscock County, Texas, on the Drannon Ranch, approximately 18.5 miles southwest of Sterling City, Texas.

54 a. DESCRIPTION OF THE ACCIDENT:

The aircraft was completely destroyed by impact, explosion and fire at an approximate cost of \$3,500,000 (without special modification). Webb FB, Big Springs, Texas, has accepted responsibility for wreckage disposal.

Terrain at the crash site is flat and covered with mesquite trees averaging 8 to 12 feet in height and 3 to 5 inches in diameter at the base.

The major crash site pattern was a small concentrated area approximately 120 feet to the left of the fuselage, 150 feet forward of the nose section, and 175 feet to the right and right forward of a reference point located at rear right wing spar and the fuselage. This pattern indicates little forward momentum and is indicative of a slowly turning flat spin to the left, in conjunction with a down-wind velocity for the entire airplane no greater than the velocity of the prevailing wind, at time of impact. The aircraft heading at time of initial impact was approximately 68° true.

Portions of the aircraft disintegrated in flight and the resultant debris fall-out pattern extended in a long narrow pattern extending approximately 25 miles in length and 3 miles in width along a course of 66° true.

All main structural components of the aircraft were accounted for and returned to the crash site for comparison and analysis. The AF Form 780 series (Form I) Navigator's log and Engineer's log were not recovered and presumed destroyed. Aircraft records necessary for completion of the investigation were obtained from the 6th Bomb Wing (H), Walker AFB, the organization reporting the aircraft on the IIO Report.

5. INVESTIGATION OF DE-FLIGHT DISINTEGRATION:

The long and narrow fall-out pattern was located in a flat scattered mesquite covered area. The first items located in the fall-out pattern were the two jet pods with pylons. Their location was 31°11'N, 101°21'W. All other items were found downwind of the location on a heading of 66° true. These items were distributed in a manner as would be expected by an extremely strong wind should the aircraft come apart at high altitude with the parts of high mass density falling first and the parts of

55 a. FINDINGS:

- (1) Crew L-22 was satisfactorily checked out in accordance with SAC Regulation 51-19.
- (2) Crew L-22 had a current standboard-check.
- (3) Crew L-22 had successfully completed SES 13 May 1955.
- (4) Crew rest time prior to the flight was adequate.
- (5) Aircraft forms indicate no discrepancies contributing to the accident.
- (6) Twenty-one Technical Orders had not been complied with at time of accident.
- (7) The crew was properly cleared at take-off on a routine "O" type training mission.
- (8) Radar Bomb Runs were successfully accomplished at San Antonio.
- (9) Severe weather developed as a squall line preceding a cold front south of Big Spring, Texas, subsequent to 2200 CST.
- (10) The squall line and severe weather moved rapidly east during the period 2200 CST to 2400 CST.
- (11) The southern end of the cold front moved eastward through Arizona, New Mexico and West Texas at approximately 25 knots velocity.
- (12) A squall line extended south from Childress, Texas, after 2100 CST to Big Spring, Texas by 2200 CST and south of Big Spring to the US-Mexico border by 2300 CST.
- (13) Area of the accident was considered by Tinker Severe Weather Warning Unit. SSW stated the squall line was inactive Abilene to San Angelo, Texas, at 2015 CST.
- (14) Severe weather was forecast for area north of the Big Spring - Abilene, Texas, line.
- (15) Severe weather consisted of heavy thunderstorms in early stages of development, no tornado cells aloft.

SECTION XIII
AF Form 14
15 Dec 54

- (16) Thunderstorms in area of original flight path were forecast and entered on the DD Form 175.
- (17) The pilot was briefed before take-off on Severe Weather Advisory No. 296.
- (18) The pilot received and acknowledged Hobbs and Walker AFB Weather and Radar Report shortly after 2245 CST.
- (19) Outer wing panels and tips, jet pods and pylons, rudder, stabilizers, ailerons, elevators and miscellaneous debris disintegrated or separated from the aircraft while in flight. These items were located away from the main crash site in a long narrow fall-out pattern 25 miles long, approximately three miles in width and along a true heading of 66° .
- (20) All major components of the aircraft were accounted for. The components located away from the main crash site were returned to the main crash area for engineering study.
- (21) All escape hatches and sighting plugs were installed at time of impact.
- (22) The aircraft collided with ground and the wing areas and nose section were completely burned. The fuselage was destroyed by impact.
- (23) There were little or no skid marks made by the aircraft upon impact.
- (24) Trees located at the rear of the aircraft were not broken, indicating a nearly vertical descent.
- (25) The rear fuselage section was 14° out of line counter-clockwise from normal fuselage center line.
- (26) Pieces of the pilot's green hose were found approximately equi-distant in various forward and side directions from the aircraft nose.
- (27) Parts of the left and right wings and wing tanks were found both forward and aft of the aircraft.
- (28) Fewer than three marks on the right wing engines were farther apart than the marks made by the left wing engines indicating the right wing was traveling faster than the left.

SECTION XIII
AF Form 14
15 Dec 54

- (29) Impact indentations in the ground made by the six reciprocating engines were approximately of the same depth.
- (30) Traces located to the left rear of the fuselage showed flash fire burns.
- (31) Five of six bodies in the unburned rear-fuselage were found in the forward right side of the pressurized section.
- (32) Nine bodies in the burned nose section were found forward and to the left.
- (33) All crew members were identified.
- (34) Propeller blade angle settings at time of impact varied from 29.5° to 30° .
- (35) The aircraft was operating on an Instrument Flight Rules Clearance 1000 ft on top at time of accident.
- (36) A position report was given to San Angelo locating the aircraft 18 miles south of San Angelo at 2244 CST at 25,000 ft.
- (37) The accident occurred at approximately 2305 CST, and the aircraft crashed at $31^{\circ}11'45''N - 101^{\circ}20'00''W$.
- (38) The landing gear and flaps were in the up position at time of impact.
- (39) Some rear compartment light bulb filaments were stretched but unbroken. This indicates they were on at time of impact. If the bulb filaments were cold at time of impact, they would not have stretched, but would have broken.
- (40) All fuel valves which were located and identified were open except the bomb bay tank and jet engine valves.
- (41) The Convair production number 374 confirmed identification of the aircraft as 52-2318.
- (42) The clearance in clearance had been obtained by the aircraft commander for portions of the flight completed prior to reporting 18 miles south of San Angelo, Texas.
- (43) Although 175 forms were filed for the two flights on 12/15/54 by the crew and aircraft, only one DD Form 175 was filed.

- (44) One right engine fire extinguisher showed evidence of not having been fired although it was found empty. The other three engine extinguishers were empty and damaged beyond analysis.
- (45) Two eye witness statements indicate there was a fire in flight; however, there is no structural evidence of in-flight fire either prior to or subsequent to time of in-flight disintegration.
- (46) Disintegration of the outer wing panels severed fuel manifold lines leading into the outer wing tanks and jet pods. These ruptured lines could dump gasoline overboard, which could vaporize and ignite, burning behind the aircraft during the descent.

55 b. CONCLUSIONS:

- (1) Captain Basinger's Crew L-22 was fully qualified in the B-36 aircraft.
- (2) The aircraft, number 52-2618, was acceptable for this flight.
- (3) The crew was flying an ordered, authorized operational training mission.
- (4) Aircraft penetrated a heavy thunderstorm in early stage of development.
- (5) The aircraft was flown into an area of severe turbulence with no apparent attempt to circumnavigate the severe weather area.
- (6) The aircraft experienced structural failure, due to overstress forces received from turbulence encountered in flight.
- (7) Loss of all control surfaces resulted in uncontrolled flight which introduced forces that prevented the crew from bail out.
- (8) The aircraft struck the ground in a flat spin to the left, destroying it by impact, explosion and fire.
- (9) All crew members received fatal injuries.

- (10) Power settings at-time of impact were less than those required to establish configuration for thunderstorm penetration.
- (11) The pilot violated AFR 60-16, Section IV, paragraph 35a, by failure to change clearance of IFR 1000' on top to an assigned altitude prior to entering IFR conditions.

56. RECOMMENDATIONS:

- F (1) A procedure be developed for immediate detection of severe weather and immediate dissemination of this information to all aircraft by and through both military and CMA facilities.
- B (2) That all pilots encountering severe weather be required to pass on to the nearest communication facility, Civil Aeronautics Authority or military, and that facility immediately relay the pilot's report to all like facilities, in the same general area, for blanket broadcast to all aircraft.
- F (3) A study be made to develop a technique and/or equipment for airborne detection of the degree of weather intensity.
- F (4) A more thorough indoctrination be given all air crew personnel on turbulent air and thunderstorm flying techniques.

MEDICAL REPORT OF AIR FORCE AIRCRAFT ACCIDENT

(If additional space is desired, use additional sheets of paper and identify by proper section and item number)

GENERAL INFORMATION

1. STATION INVESTIGATING ACCIDENT Walker Air Force Base, N. M.		2. ASSIGNED STATION OF AIRCRAFT Walker AFB, New Mexico		3. NUMBER OF MILES FROM ACCIDENT TO INVESTIGATING STATION 190 nautical miles	
3. LOCATION OF ACCIDENT 19-1/2 mi. SW of Sterling City, Texas		4. ACFT TYPE, MODEL, SERIES AND SERIAL NUMBER B-36J #52-2618		6. DATE OF ACCIDENT 25 May 55	
7. HOUR (Local) Approx 2300 CST					

8. DESCRIPTION OF FACTORS AND EVENTS LEADING TO ACCIDENT
Round robin mission from Walker Air Force Base, New Mexico:
 Aircraft passed through area of severe thunderstorm activity at about 2245C to 2300C hours, giving normal report at 25,000 indicated, 1,000 on top at 18 miles South of San Angelo radio, upon contact with San Angelo, Texas, radio at 2246C hours. Aircraft was seen descending and was observed to have crashed at approximately 2300C hours, with a large explosion. Distribution of fragments of the aircraft indicates that the aircraft partially disintegrated in the air. There was no known distress signal and the crew members apparently had little opportunity to evacuate the aircraft prior to ground contact.

II. EQUIPMENT AND AIRCRAFT STRUCTURES

9. FIXED SEATS				15. ANTI G SUIT					
NUMBER 10 seats		NUMBER OCCUPIED Unknown		NUMBER FAILED Unknown		AVAILABLE TO ALL PERS YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		USED BY ALL PERSONNEL YES <input type="checkbox"/> NO <input type="checkbox"/> NUMBER N/A	
7 bunks		Unknown		Unknown					
10. EJECTION SEATS N/A				16. PARACHUTES					
USED N/A FAILED		NO. AVAIL (Armed)		NO. USED DOWNWARD		NO. USED UPWARD		TYPE N/A	
YES <input type="checkbox"/> NO <input type="checkbox"/> NUMBER		None		N/A		N/A		FAILED YES <input type="checkbox"/> NO <input type="checkbox"/> NUMBER N/A	
NO <input type="checkbox"/> YES <input type="checkbox"/>									
11. CABIN PRESSURIZATION				17. AUTOMATIC LAP BELT RELEASE					
AVAILABLE TO ALL PERS <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		USED BY ALL PERSONNEL <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		FAILED Unk.		TYPE 1, back; 1 chest		USED BY ALL PERSONNEL YES <input type="checkbox"/> NO <input type="checkbox"/> NUMBER	
12. OXYGEN SYSTEM				18. OTHER PERSONNEL EQUIPMENT N/A					
AVAILABLE TO ALL PERS <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		USED BY ALL PERSONNEL <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		FAILED Unk.		TYPE A-13A		NUMBER	
DATE SERVICED 25 May 55		TYPE D-2		USED THIS FLIGHT TIME Unk. AMT Unk.		AVAILABLE TO ALL PERS YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		USED BY ALL PERSONNEL YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> NUMBER 0	
13. OXYGEN MASK				19. SPECIAL FACTORS WHICH CONTRIBUTED TO OR PREVENTED INJURY (List any items of personal or aircraft equipment details of structure, incidents such as being trapped in plane, or any other factors which aided or impeded escape from aircraft.)					
AVAILABLE TO ALL PERS <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		USED BY ALL PERSONNEL <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		TYPE A-13A		FIT Unk.		NUMBER	
FAILED Unk.		NUMBER USED		FIT Unk.		USED		FAILED	
YES <input type="checkbox"/> NUMBER FAILED				YES <input type="checkbox"/> NUMBER POORLY FITTED					
NO <input type="checkbox"/>				NO <input type="checkbox"/>					
14. PROTECTIVE HELMET				20. SPECIFICALLY DESCRIBE DAMAGE TO COCKPIT					
AVAILABLE TO ALL PERS YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		USED BY ALL PERSONNEL YES <input type="checkbox"/> NO <input type="checkbox"/> NUMBER N/A		Completely destroyed by impact and fire.					
TYPE N/A		FAILED YES <input type="checkbox"/> NO <input type="checkbox"/> NUMBER N/A		SEATS, SHOULDER HARNESS, SAFETY BELT: All but metal portion of harness was destroyed by fire in front compartment (nose); none harness in aft compartment was intact, but unbuckled; emergency exits, harness, and A-6 was fastened.					
				All forward stations destroyed. Rear compartment stations suffered no fire damage, but were severely damaged by impact.					
				EMERGENCY EXITS, HARNESS, SAFETY BELT: Green house burned out in front; unable to locate front escape hatches; one rear escape hatch forced out of fittings and one (left) in place.					
				PASSENGER CABIN N/A					

The apparent extremely severe forces that came to play on all equipment in both front and aft compartments, which so destroyed and disarranged the interior of aircraft, makes this section difficult, if not impossible, to complete.

20. SPECIFICALLY DESCRIBE DAMAGE TO COCKPIT

Completely destroyed by impact and fire.

SEATS, SHOULDER HARNESS, SAFETY BELT: All but metal portion of harness was destroyed by fire in front compartment (nose); none harness in aft compartment was intact, but unbuckled; emergency exits, harness, and A-6 was fastened.

All forward stations destroyed. Rear compartment stations suffered no fire damage, but were severely damaged by impact.

EMERGENCY EXITS, HARNESS, SAFETY BELT: Green house burned out in front; unable to locate front escape hatches; one rear escape hatch forced out of fittings and one (left) in place.

PASSENGER CABIN
N/A



12

B-57J 25 MAY 55 52-2318 #5 JAW
Facing Toward Rear of A/cft. Note Fuel Is Reversed