
DTC	C2176/76	Receiver Error
-----	----------	----------------

DESCRIPTION

The signals are transmitted to the tire pressure warning antenna and receiver on the body as radio waves and then sent to the tire pressure warning ECU.

DTC No.	DTC Detection Condition	Trouble Area
C2176/76	 When either of following detected: EEPROM in tire pressure warning ECU malfunction Terminal RF5V shorted to ground 	 Tire pressure warning antenna and receiver Tire pressure warning ECU Wire harness or connector

WIRING DIAGRAM




NOTICE:

- When replacing the tire pressure warning ECU, read the IDs stored in the ECU using the intelligent tester and note them down before removal (See page TW-28).
- It is necessary to perform initialization (See page TW-15) after registration (See page TW-11) the transmitter IDs into the tire pressure warning ECU after the ECU have been replaced.

1

CHECK HARNESS AND CONNECTOR (TIRE PRESSURE WARNING ECU - TIRE PRESSURE WARNING RECEIVER)



- (a) Replace the tire pressure warning ECU with a normally functioning or new one.
- (b) Register the transmitter IDs again (See page TW-11).
- (c) Perform TEST MODE PROCEDURE (See page TW-17).
- (d) Perform the forcible transmission of all the transmitter IDs.

Α

(e) Confirm that DTCs C2181/81 to C2185/85 are cleared. **Result**

Result	Proceed to
DTCs all cleared	A
DTCs not cleared	В

REPLACE TIRE PRESSURE WARNING ECU

В

REPLACE TIRE PRESSURE WARNING ANTENNA AND RECEIVER

