



DTC No.	DTC Detecting Condition	Trouble Areas
C1256/56	Fluid pressure inside the accumulator drops below the specification value.	<ul> <li>Hydraulic brake booster</li> <li>Hydraulic brake booster pump motor</li> <li>Hydraulic brake booster pump motor circuit</li> <li>Accumulator pressure sensor</li> </ul>

|--|

- (b) Turn the ignition switch to OFF.
- (c) Depress the brake pedal more than 20 times.
- (d) Turn the ignition switch to the ON position.
- (e) Wait for 99 seconds.
- (f) Check if the same DTCs are recorded.





## **REPLACE MASTER CYLINDER SOLENOID**

BC