


Slip Indicator Light Remains ON

DESCRIPTION

- The SLIP indicator blinks when any of the TRAC, VSV and AUTO LSD operate.
- When the system fails, the SLIP indicator light illuminates to warn the driver.

WIRING DIAGRAM



BC

HINT:

Start the inspection from step 1 when using an intelligent tester and start from step 2 when not using an intelligent tester.

1 CHECK DTC

(a) Check the DTCs.


Result	Proceed to
DTC not output	A
DTC output	B

B REPAIR CIRCUITS INDICATED BY OUTPUT DTCS


A

2 CHECK HARNESS AND CONNECTOR (SKID CONTROL ECU - COMBINATION METER)

Combination Meter (harness side view)



Skid Control ECU (harness side connector)



- (a) Disconnect the skid control ECU connector.
- (b) Disconnect the combination meter connector.
- (c) Measure the resistance.

Standard

Tester Connection	Specified Condition
S1-34 (IND) - C9-36	Below 1 Ω

- (d) Measure the resistance.

Standard

Tester Connection	Specified Condition
S1-34 (IND) - Body ground	10 kΩ or higher

- (e) Reconnect the combination meter connector.
- (f) Reconnect the skid control ECU connector.

NG REPAIR OR REPLACE HARNESS OR CONNECTOR

BC

OK

3 INSPECT COMBINATION METER ASSEMBLY

- (a) Check the combination meter system (See page ME-8).

OK:

Combination meter is normal.

NG REPLACE COMBINATION METER ASSEMBLY

OK

REPLACE MASTER CYLINDER SOLENOID