

Water Quality Monitoring Results at the Markland Hydroelectric Project (FERC No. 2211) 2011 - 2015




Presentation to Ohio River Valley Water Sanitation Commission Technical Committee,
Pittsburgh, Pennsylvania, June 7, 2016

OHIO RIVER MAINSTEM NAVIGATION SYSTEM

General Plan and Profile

Markland Locks and Dam

- River Mile 531.5
- Cincinnati ~50 miles upriver, Louisville ~50 miles downriver
- Markland pool extends 95 river miles




Project Operations



- Project originally licensed in 1961, construction of locks & dam completed 1964
- Hydro completed with commercial operation beginning in 1967
- Three 21.6-MW Kaplan turbine/generator units, 64.8-MW licensed capacity
- Hydraulic capacity of 40 kcfs (3 units at 34 ft head)
- Run-of-release operation: Per MOA, USACE stipulates how much water is available after navigation needs and maintenance of the pool elevation are met.


Four-Blade Kaplan runner being installed at Markland

Turbine power rating



Markland Tainter Gate Spillage – Influence on Water Quality

- The Markland Dam is 1,395 feet long, 42 feet high, and consists of twelve 42-foot high Tainter gates; each 100 feet wide.
- At low flows / low velocities, the sub-surface flow under Tainter gates generates limited turbulence and re-aerates relatively inefficiently



Markland Project 401 Water Quality Certification

- IDEM Section 401 WQ Certification granted December 8, 2009; re-issued January 22, 2010; June 21, 2012
- FERC Order issuing New License, September 7, 2010; effective May 1, 2011, adopting 401 WQ Certification conditions

IDEM Policy & Water Quality Standards

- Dissolved oxygen (DO) standards apply to hydroelectric generation releases
- *Concentrations of dissolved oxygen shall:*
 - *(A) average at least five (5.0) milligrams per liter per calendar day; and*
 - *(B) not be less than four (4.0) milligrams per liter at any time.*

327 IAC 2-1-6

FERC License and 401 Requirements

1. (2010) Install continuous WQ monitors at Project
2. (2011-2015) Conduct 5-years of WQ monitoring to assess compliance with WQS and potential need for aeration. Reporting required for March-October continuous monitoring (monthly, annually) and river profiling (annually)
3. (Feb 2014) Provide summary of initial 3 years of monitoring and outline options to address instances where DO WQS not met
4. (June 28, 2016) Within 120 days after of the 5-year DO Monitoring Plan, submit to IDEM a plan and implementation schedule for compliance with WQS

FERC License and 401 Requirements

- ✓ 1. (2010) Continuous monitors installed at Project
- ✓ 2. (2011-2015) Conduct 5-years of WQ monitoring to assess compliance with WQS and potential need for aeration. Reporting required for continuous monitoring (monthly, annually) and river profiling (annually)
- ✓ 3. (Feb 2014) Provide summary of initial 3 years of monitoring and outline options to address instances where DO WQS not met
- 4. (June 28, 2016) Within 120 days after of the 5-year DO Monitoring Plan, submit to IDEM a plan and implementation schedule for compliance with WQS

FERC License and 401 Requirements

- 5-Year Study Initial Question: Are DO levels of water released via the Markland Dam gates “substantially different” than the DO levels of water passed through the project?
- The Markland FERC Project License requires consultation with IDEM, ORSANCO, and USACE Louisville District prior to submitting to IDEM for approval a plan and implementation schedule assuring Project compliance with state water quality standards, if needed.




Five-Year Study Objectives

- Determine extent that Project tailwaters meet WQS
- Compare hydro tailwater DO to spillage DO and assess potential for reaeration when tailwater DO is below the WQS



Study Design & Methods

- Seasonal continuous WQ monitoring by USGS Kentucky Water Science Center, Louisville, KY



The screenshot shows the USGS National Water Information System (NWIS) web interface. At the top, the USGS logo is displayed with the tagline "science for a changing world". Below the logo, the text "National Water Information System: Web Interface" and "USGS Water Resources" is visible. A navigation menu includes "Click to hide News Bulletins" and "Click to hide state-specific text". The main content area is titled "USGS 03277200 OHIO RIVER AT MARKLAND DAM NEAR WARSAW, KY" and "Stream Site". A "DESCRIPTION:" box contains the following information: Latitude 38°46'29", Longitude 84°57'52" NAD27, Gallatin County, Kentucky, Hydrologic Unit 05090203, Drainage area: 83,170.0 square miles, and Datum of gage: 407.26 feet above NGVD29.




15-minute recording interval,
March 1 – October 31

● WQ Monitors







- Low-Flow Ohio River Vertical Profile Sampling (3X Annually)




2011 – 2015 Meteorology and River Flows



Air Temperatures (CVG) – Monthly Average Departure from Normal




Ohio River Daily Flows March – October of 2011 – 2015




Results of Continuous Monitoring







Tailrace Daily Average Water Temperatures, 2011 - 2015




Markland Tailrace Daily Average DO, 2011 - 2015







Daily Average DO at the 4 Markland Sites, 2011 - 2015



Tailrace DO: Frequency Distribution of Approved Data 2011-2015




All 4 Markland Sites: Frequency Distribution of Approved Data 2011-2015



Hydro Tailrace Continuous Monitoring DO Statistics


- Five monitoring seasons combined data:
 - 114,857 individual Markland tailrace DO readings
 - 1,196.4 days represented (March – October)
- 100% compliance with instantaneous DO of 4.0 mg/L
- 6 total days with daily average DO < 5.0 mg/L
 - 2 days where mean DO was < 4.9 mg/L; (Min. 4.4 mg/L on July 20, 2012 and September 11, 2015)

River Transect Water Quality Vertical Profiles




Vertical Profiles: Water Temperature

- Profile temperatures always met Ohio River mainstem WQS
- Markland Reservoir vertical profiles consistently show near-isothermal conditions, which ensures downstream temperatures will be similar



Vertical Profiles: Dissolved Oxygen

- Profile DO concentrations always met Ohio River mainstem WQS
- In low flow scenarios, upstream DO saturation was typically enhanced in the upper water column due to influence of atmospheric exchange and daytime photosynthesis






Markland Generation Releases – Influence on Water Quality As Demonstrated by Transect Profile Sampling

Generation releases result in a depth-integrated tailwater DO

- Upstream surface (0.3 m) DO: 7.2 mg/L
- Upstream profile (0.3 to 11 m) average DO: 6.7 mg/L

- Tailwater profile average DO: 6.7 mg/L
- Tailwater surface DO: 6.7 mg/L





Minimal DO Boost from Tainter Gate Spillage

Markland pool 455 ft msl
 Tainter gate bottom sill 427 ft msl
 Profile depth equivalent 28 ft or 8.5 m

Spillage DO reflects US water column averaged DO from the top ~1/3 of the water column, increased by a minor, DO saturation and flow-dependent reaeration component.

“A *submerged* hydraulic jump below a gated structure has minimal oxygen transfer.”

Hettiarachchi et al. (1997)



Low Flow Tainter Gate Spillage


Spillage releases result in downstream [DO] consistent with minor reaeration of a depth-integrated release from the top ~1/3 of the water column

Example Conditions – Markland Spillage

Average Upstream Profile DO:
6.7 mg/L,
Percent DO saturation: 84%


Downstream DO:
7.1 mg/L
Percent DO saturation: 90%

**Net increase of 0.4 mg/L,
6% increase in saturation**



Comparing Generation Release to Gate Spillage DO

- Based on 2011-2015 channel transect data, the relative increase in DO from spillage was typically 0.3 to 0.5 mg/L.
- Even with generation-dominated flows, downstream DO met or exceeded the upstream water column median DO



Low-Flow Channel Transect Profiling – Spillage Aeration Assessment from Observations With and Without Hydro Generation

- Under low flows, Tainter gates are typically set open at 1 foot; additional gates will then be opened at 1 foot sequentially as needed
- Typically observe 0.3 to 0.5 mg/L increase in DO from Tainter gate underflow releases compared to hydro generation flow releases
- Hydro generation shutdown can lead to localized low DO water upstream when trash accumulation is substantial



Site-Specific Considerations



Characterizing Spillage: Markland spillways lack a hydraulic jump to enhance reaeration

Markland





McAlpine, Lower




Re-Aeration Potential

- Empirically determined gas transfer efficiency and 95% C.I.

(Hettiarachchi et al. 1997)




Local and Transient Effects of Debris on Water Quality








Markland Forebay DO and Generation Shutdowns, 2015



3-Mile Downstream
Transect During Spillage-
Only Flow vs Generation
Flow, August 27, 2015



Five-Year Study Findings

- Instantaneous WQS of 4 mg/L DO met without exception in hydro tailwaters (114,857 readings)
- Hydro tailwaters met the daily average DO WQS of 5 mg/L 99.5 percent of the time (maximum among monitoring sites)
- Daily average DO below 5 mg/L only observed in summers of 2012 and 2015
 - 2012: 3 days with < 5 mg/L average; 2 days had a mean DO of 4.9 mg/L, with one day averaging 4.4 mg/L
 - 2015: 3 days with < 5 mg/L average; 2 days had a mean DO of 4.9 mg/L, with one day averaging 4.4 mg/L

Perspective After 5-Year Study

- The instantaneous DO WQS (4 mg/L) was ALWAYS met
- Exceptionally infrequent and relatively brief circumstances when daily average DO WQS not met
- WQ from Tainter gate spillage not “substantially different” from generation release WQ
- Localized water quality impairment attributed to high-BOD water release from accumulated debris can be triggered by hydro shutdowns

Benefits of Markland Hydropower

- As a renewable and emissions-free source of energy, hydro generation provides reliable, carbon-free electric power 24/7 (except when flow-limited).
- Markland generation is base-loaded. Replacement power would likely be derived from regional generation sources having CO₂ and other emissions.




2016 Proposed State Water Quality Compliance Plan and Schedule

- Submitted to agencies for consultation May 31, 2016
- Duke to file Plan & Schedule w/ FERC July, 2016
- IDEM implementation under authority of 401 WQC
- Duke requesting full Plan implementation in 2017

Compliance Plan and Schedule Elements

- Continued USGS Monitoring, June 1 – October 31
 - Tailrace DO compliance
 - Forebay WQ trending
- Provision for independent accuracy checks of USGS instrumentation
- Interim triggers for hydro operation curtailment
 - < 5 mg/L (daily average) trigger
 - < 4 mg/L (instantaneous) trigger
 - Potential for future turbine aeration removing triggers
- Provisions for electric grid emergencies, long-lived degraded water quality episodes

Flowchart: Interim hydro operational response to tailrace DO concentration




Rationale of Plan Elements

- ***June – October monitoring term:***
Five-year minimum tailwater DO, March through May = 6.5 mg/L
(Five-year June minimum = 5.3 mg/L)
- ***Independent DO checks:***
Ability to overcome out-of-calibration conditions and typical 1-2 day response by USGS
- ***Interim triggers for generation curtailment:***
Triggers to curtail hydro generation nullified when WQ from replacement, aerated Markland units (if implemented) is demonstrated to approximate WQ from Tainter gate spillage

Rationale, continued

Why set the daily average trigger at >32 cumulative ($4 \text{ mg/L} \leq \text{DO} < 5 \text{ mg/L}$) readings?
Historical data distribution shows this will be protective to the extent practical.



Rationale, continued

Why set the < 4 mg/L trigger at two successive readings?

- Due to relative improbability of occurrence, the approach can screen out spurious data
- Avoids prompting a USACE response in opening gates based on a single number
- Allows opportunity for independent verification of apparent low tailrace DO



Acknowledgements

- USGS, Kentucky Water Science Center
 - Mike Griffin
 - Tom Ruby
 - Molly Lott
- USACE, Markland Locks and Dam
 - Gary Birge, Markland Lockmaster
- Duke Energy, Markland Project
 - Tami Styer
 - Andy Leininger
 - Kyle Meyer
 - Phil Sexton
 - Bill Chanley
 - Glenn Long
 - Courtney Flowe

