



SPACE SHUTTLE PROGRAM
Space Shuttle Projects Office (MSFC)
NASA Marshall Space Flight Center, Huntsville, Alabama



STS-113/ET-116 Flight Readiness Review

External Tank Project



October 31, 2002



Overview

Presenter Jerry Smelser, NASA/MP31

Date October 31, 2002 Page 2

- **Limited Life Component Status**
 - All items within required life through scheduled launch date plus 90 days
- **No Significant Changes**
- **Special Topic**
 - STS-112/ET-115 Bipod Ramp Foam Loss
- **Significant Processing Anomalies**
 - LO2 Feedline Repair Using BX-265 Foam
 - Undersized Intertank Stringers
- **Readiness Statement**

STS-112/ET-115 Bipod Ramp Foam Loss

Presenter Jerry Smelser, NASA/MP31


Date October 31, 2002 Page 3

• Issue

- Foam was lost on the STS-112/ET-115 -Y bipod ramp ($\approx 4'' \times 5'' \times 12''$) exposing the bipod housing SLA closeout

• Background

- ET TPS Foam loss over the life of the Shuttle Program has never been a "Safety of Flight" issue
- More than 100 External Tanks have flown with only 3 documented instances of significant foam loss on a bipod ramp





STS-112/ET-115 Bipod Ramp Foam Loss

Presenter Jerry Smelser, NASA/MP31

Date October 31, 2002 Page 4

• Rationale for Flight

- Current bipod ramp closeout has not been changed since STS-54 (ET-51)

- The Orbiter has not experienced “Safety of Flight” damage from loss of foam in 112 flights (including 3 known flights with bipod ramp foam loss)

- There have been no design / process / equipment changes over the the last 60 ETs (flights)

- All ramp closeout work (including ET-115 and ET-116) was performed by experienced practitioners (all over 20 years experience each)

- Ramp foam application involves craftsmanship in the use of validated application processes

- No change in Inspection / Process control / Post application handling, etc


- Probability of loss of ramp TPS is no higher/no lower than previous flights

- ***The ET is safe to fly with no new concerns (and no added risk)***



Prior to Foam Closeout

After Final Foam Trim



Bipod Attach Fitting



LO2 Feedline Repair Using BX-265 Foam

Presenter Jerry Smelser, NASA/MP31


Date October 31, 2002 Page 5

• Issue

- LO2 feedline foam insulation (BX-250) debond at Sta. 1623
 - Repair required based on foam insulation bond-adhesion (plug-pull) test evaluation

• Background

- Implemented inspection of all BX-250 LO2 feedlines
 - Plug pulls performed to verify foam strength or identify debond area
- Plug pulls at 3 of 4 stations on ET-116 accepted based on
 - Measured values
 - Engineering data
 - Prior flight experience
 - Lowest value of 13.9 psi (35 psi required) at Sta. 1129 accepted based on analytical assessment and past flight performance
- One location required repair at Sta. 1623
 - Repair accomplished using BX-265 foam
 - First time flight usage
 - Fully qualified material
 - Planned for use on ET-120





LO2 Feedline Repair Using BX-265 Foam

Presenter Jerry Smelser, NASA/MP31


Date October 31, 2002 Page 6

• Rationale for Flight

- Physical and mechanical properties for BX-265 similar to BX-250 (and much greater than requirements)
 - Mechanical
 - Density, flammability, specific heat, coefficient of thermal expansion (CTE) and Poisson's ratio
 - Tensile, compressive, and shear strength, combined tension and flexure @ cryogenic temperature (cryoflex)
 - Thermal conductivity
 - Recession response
- Production Verification
 - Cell validation
 - Full scale demonstration
- Plug pulls on ET-116 repair area indicated strong bondline
 - Actual values: 61.9 and 41.2 psi (35 psi required)
- ***ET-116 feedline acceptable for flight***

Repair Area





Undersized Intertank Stringers

Presenter Jeff Pilet, LMSSC-MO/4130


Date October 31, 2002 Page 7

• Issue

- Undersized Intertank sheet metal stringers potentially installed on completed ETs
 - Final stock material thickness verification not performed following complete part processing at Aerochem


• Background

- Stringers in process flow identified at the low end or below minimum thickness tolerance
 - Stock material thickness verification performed at material receipt from Dynamic Metal Forming (DMF)
 - Stock material met receiving inspection requirement (0.061 in. min.)
 - Majority of stringers are locally chem-milled ('pocketed') to achieve final part thickness requirements
 - 'Pocketed' thicknesses are verified after final processing
 - Remaining stock material areas (non-pocketed) are chemically 'etched' during the cleaning and part marking process
 - 'Non-pocketed' stringer thicknesses were not re-verified after final processing
- Process investigation performed and shows that the normal processing of 'non-pocketed' stringer regions could remove an additional 0.0028"



Undersized Intertank Stringers

Presenter Jeff Pilet, LMSSC-MO/4130	
Date October 31, 2002	Page 8





Undersized Intertank Stringers

Presenter Jeff Pilet, LMSSC-MO/4130

Date October 31, 2002 Page 9

• Actions Taken

- Initiated thickness verification of accessible stringers (≈ 1500 parts)
 - Stringers installed on ETs with end bays exposed and loose parts
 - Performed at least 1 measurement per stringer end
 - Thickness measurements consistent along stringer length
- Performed statistical analysis (2070 measurements) to derive 3 sigma minimum thicknesses
 - Forward vs aft end measurements
 - 'Pocketed' vs 'non-pocketed' parts
 - Minimum measured in critical margin areas is 0.0568 in.
 - 3σ low thickness in critical margin areas is 0.0559 in.
- Initial analysis using an assumed low bound minimum thickness (0.0530") showed local areas of negative ultimate stability margins of safety (column buckling) near the cryo 'end bay' regions
 - Low margin areas isolated to aft region of Panel 1 and the forward regions of Panels 2/3 and 6/7
 - Revisions were made to the analysis methodology to reduce conservatisms and achieve more realistic structural margins of safety for these regions



Undersized Intertank Stringers	Presenter Jeff Pilet, LMSSC-MO/4130	
	Date October 31, 2002	Page 10

• **Rationale for Flight**

• Analysis

- Analysis methodology for Panel 1 region was revised to use time consistent thermal gradient and applied vehicle loads

- Results of analysis shows adequate structural Factor of Safety

<u>Design</u>	<u>t stringer (in.)</u>	<u>FS</u>	<u>FS required</u>
• Engineering requirement	0.059 min.	1.55	1.40
• 3σ Low	0.056 min.	1.48	1.40
• Lower bound	0.053 min.	1.41	1.40

- Analysis methodology for Panel 2/3 and 6/7 regions was revised to assume the critical stringer is 'ineffective' resulting in load redistribution to adjacent structure

- Results of analysis shows adequate structural Factor of Safety

<u>Design</u>	<u>t stringer (in.)</u>	<u>FS</u>	<u>FS required</u>
• Engineering requirement	0.059 min	1.54	1.29
• 3s Low	0.056 min	1.48	1.29
• Lower bound	0.053 min	1.29	1.29

• Test

- Column buckling analysis conservatively correlated to previous structural test results
 - Test demonstrated capability ~ 13% greater than analytical prediction



Undersized Intertank Stringers

Presenter Jeff Pilet, LMSSC-MO/4130

Date October 31, 2002 Page 11

• Rationale for Flight - Summary

- Column buckling analysis methodology correlates conservatively with structural test results
- Revised analysis methodology shows positive ultimate margins of safety using conservative lower bound stringer thickness values
- ***ET-116 Intertank Stringers meet design requirements and are acceptable for flight***



Readiness Statement	Presenter	
	Date October 31, 2002	Page 12

The External Tank, ET-116, is certified and ready for STS-113 flight pending completion/closure of open and planned work